9/28/21, 9:43 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21009226/GQF3E2

Date: 28/09/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210015300

Claimant Vehicle

FREEPORY

FREEPORY

CROSSESSES AND ARRIVATION OF THE POLICY PROPERTY PROPERTY OF THE POLICY PROPERTY PROPERTY PROPERTY PROPERTY PROPERTY PROPERTY PROPERTY PROPERTY PROPERTY PROPER

No: FBE5897X Insured Vehicle No: SFC2088Y

Date of Loss: 01/08/2021 Nature of Claim: TP Claim No: 0037044934SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBE5897X

Make & Model: YAMAHA FZ1-N, 998cc Engine No: N513E051962

Reg. Date: 11/06/2010 (Man. Year: 2010) Chassis No: JYARN165000016069

Colour: Black Odometer: 0 km

Engine Capacity: 998 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70Z R17 Rear Tyre Size: 190/55Z R17
Front Left Side: Bridgestone 4 mm Rear Left Side: Pirelli 4 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/09/2021

Soon Hin Motor Pte Ltd (HQ)

Date Inspected: 02/09/2021 Inspected At: BLK 1018 YISHUN INDUSTRIAL PARK A #01-342

Singapore 768760

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value : \$10,000.00 OMV : \$9,508.00 PARF Rebate (1): \$0.00 \$4,352.00 Quota Premium Paid: COE Rebate (2): \$3,786.00 Total Rebate (1) + (2) = : \$3,786.00

The total amount incurred will be Market Value \$10,000.00 minus Total Rebate \$3,786.00 = \$6,214.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Adjuster Report

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

9/28/21, 9:43 AM

Report was unsubmitted during this print-out.

< END OF ESTIMATES >