

REPAIR ESTIMATE*

VEHICLE NO SHA2499G

MAKE 17.03.2016 REG.

MODEL I-40

DATE 27.08.2021

CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$1,052.20
1	HEAD LAMP LH			\$1,800.00
10	BUMPER CLIP			\$22.00
1	FRONT BUMPER GRILLE LH			\$93.60
1	FRONT BUMPER BRACKET TOP LH			\$22.80
1	FRONT FENDER SHIELD LH		nec	\$174.90
1	FRONT WHEEL COVER LH			\$217.20
1	FRONT FENDER RH			\$663.00
	SUB TOTAL			\$4,045.70
	20.00%			\$809.14
				\$3,236.56
1	FRONT FENDER ADVERTISEMENT			\$100.00
				\$100.00
	Labour Charge			
	Panel Beating			\$560.00
	Spray painting			\$600.00
	Reset front wheel alignment			\$60.00
	Check Lighting			\$60.00
	TOTAL LABOUR			\$1,280.00
	ESTIMATE TOTAL			\$4,616.56
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Theran Lkh

30/8/21 1700

82235769

theran@lkh auto. com

3 days w/p

1/5 after repair photos

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date: