

Our Job Ref No : 305484605
Date : 02/09/21

ENGINEERING
ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508060
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : THEVAN


Fax :


Vehicle Reg No. : SHA3553B

Date of Accident : 27/08/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- GBH4681S
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$590.10
 - (b) Labour Charges \$660.00
 - Total for Part-By-Part Repair Cost** \$1,250.10
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : 
Name : THEVAN
Date : 7/9/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR ESTIMATE*

VEHICLE NO SHA3553B

27/08/21

MAKE 27.08.2020

LIM TENG NTUC

MODEL IONIQ G3

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40 Xr
1	REAR BUMPER SIDE BRACKET RH		\$55.80 Xr
1	REAR BUMPER CENTRE MOULDING		\$451.25 /cut
1	REAR BUMPER REFLECTOR RH		\$41.45 X Svc
1	REAR BUMPER TOW COVER		\$98.80 X Svc
10	REAR BUMPER CLIPS		\$22.00 /ncc
2	NUMBER PLATE LAMP LH/RH		\$170.60 X Svc
1	REAR FOG LAMP		\$201.50 X Svc
	SUB TOTAL		\$1,500.80
	20.00%		\$300.16
	DISCOUNTED TOTAL		\$1,200.64
1	REAR REVERSE SENSOR		\$180.00 /cut
1	REAR NUMBER PLATE W/HOLDER		\$55.00 /cra
1	REAR BUMPER MAT		\$50.00 X Svc
			\$285.00
	Labour Charge		
	Panel Beating		\$450.00 350
	Spray Painting Charge		\$300.00 250
	Tuff Kote		\$60.00 30
	Remove/refix Reverse sensor		\$60.00 30
	TOTAL LABOUR		\$870.00
	ESTIMATE TOTAL		\$2,355.64
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will			
be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Thuan Lkh
 thuan@lkhauto.com
 82235769
 2 days wp
 30/8/21 1645
 P/P & bfo paint photos

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 01.09.2021
Time: 11:42:08
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305484605
REGN NO : SHA3553B
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 27.08.2020
DATE/TIME IN : 28.08.2021 10:40
ACCIDENT DATE : 27.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 28-01-0104-2029-A	REAR NO.PLATE W/TRIM CVR	1	55.00	10.00	49.50
0002 04-01-0104-2533-G	REAR BUMPER CTR MOULDING	1	451.25	20.00	361.00
0003 04-01-0101-0111-G	REAR NUMPER CLIPS	10 L	22.00	20.00	17.60
0004 09-01-9999-0068-A	REVERSE SENSOR	1	180.00	10.00	162.00

SUB-TOTAL : 590.10

JOB NATURE

0000 PB	PANEL BEATING-SHA3553B	350.00
0001 SP	SPRAYPAINT CHARGE	250.00
0002 20-00	TUFF COAT ON AFFECTED PARTS.	30.00
0003 L	R/I REVERSE SENSORS	30.00

SUB-TOTAL : 660.00