

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3553B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	REAR BUMPER SIDE BRACKET RH	TO REPAIR SEE LABOUR	55.80	-
1	REAR BUMPER CENTRE MOULDING	CUT	451.25	451.25
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	41.45	-
1	REAR BUMPER TOW COVER	SERVICEABLE	98.80	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
2	NUMBER PLATE LAMP LH/RH @\$85.30	SERVICEABLE	170.60	-
1	REAR FOG LAMP	SERVICEABLE	201.50	-
	LESS 20% DISCOUNT		-300.16	-94.65
			1,200.64	378.60
	NETT ITEMS			
1	REAR REVERSE SENSOR (N)	CUT	180.00	180.00
1	REAR NUMBER PLATE W/HOLDER (N)	CRACKED	55.00	55.00
1	REAR BUMPER MAT (N)	SERVICEABLE	50.00	-
	LESS 10% DISCOUNT		-	-23.50
			285.00	211.50
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR BUMPER SIDE BRACKET RH.		450.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	TUFF KOTE.		60.00	30.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	30.00
			870.00	660.00
	GRAND TOTAL		2,355.64	1,250.10





Page No.:2 of 2

## RECOMMENDED COST OF REPAIRS (CONFIRMED) 1,250.10

Report Ref No. NS/INC21009231/Vtcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**