



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 4316H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	REAR BUMPER SIDE BRACKET RH	SERVICEABLE	55.80	-
1	REAR BUMPER CENTRE MOULDING	CUT	451.25	451.25
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	41.45	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-205.98	-94.65
			823.92	378.60
	<u>NETT ITEMS</u>			
1	REAR REVERSE SENSOR (N)	SERVICEABLE	180.00	-
	LESS 10% DISCOUNT		-18.00	-
			162.00	-
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER MAT (SN)	SERVICEABLE	50.00	-
			50.00	-
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		450.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	TUFF KOTE.		60.00	20.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	30.00
			870.00	650.00
	GRAND TOTAL		1,905.92	1,028.60
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,028.60

Report Ref No. NS/INC21009232/Vqcn2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.