

Our Job Ref No : 305484919Date : 02/09/21**FINALIZATION FORM**To : LKK

Fax

Attn : THEVANVehicle Reg No. : SHB4316H30/08/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows. -

2 The repair job shall bill to: NTUC FBR6368G

2 The finalized amount shall be:

(a) Spare Parts after List discount \$378.60(b) Labour Charges \$650.00**Total for Part-By-Part Repair Cost** \$1,028.60(c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: _____
Final Lumpsum Repair cost _____3. Estimated normal period for repairs: 2 working days.4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : _____

Name : CHIANGTel : 62148314Fax : 65468156Signature : Name : ThevanDate : 7/9/21**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR ESTIMATE*

VEHICLE NO SHB4316H

30/08/21

MAKE 25.10.2019

CHIANG/NTUC

MODEL IONIQ G3

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40 X
1	REAR BUMPER SIDE BRACKET RH		\$55.80 X SVC
1	REAR BUMPER CENTRE MOULDING		\$451.25 / Cut
1	REAR BUMPER REFLECTOR RH		\$41.45 X SVC
10	REAR BUMPER CLIPS		\$22.00 / n/c
	SUB TOTAL		\$1,029.90
	20.00%		\$205.98
	DISCOUNTED TOTAL		\$823.92
1	REAR REVERSE SENSOR		\$180.00 / Cut
1	REAR BUMPER MAT		\$50.00 / SVC
			\$212.00
	Labour Charge		
	Panel Beating		\$450.00 350
	Spray Painting Charge		\$300.00 250
	Tuff Kote		\$60.00 20
	Remove/refix Reverse sensor		\$60.00 30
	TOTAL LABOUR		\$870.00
	ESTIMATE TOTAL		\$1,905.92
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Thuan Lkh

thuan@lkhauto.com

82235769

2 days wp

P/P bfr paint photos

31/8/21 1615

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305484919
REGN NO : SHB4316H
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 25.10.2019
DATE/TIME IN : 30.08.2021 15:30
ACCIDENT DATE : 30.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2533-G MOULDING ASSY-RR BUMPER C 1 451.25 20.00 361.00 ✓
0002 04-01-0101-0111-G BUMPER COVER CLIP REAR 10 L 22.00 20.00 17.60 ✓


SUB-TOTAL : 378.60

JOB NATURE

0000 PB PANEL BEATING-Shb4316h 350.00 ✓
0001 SP SPRAYPAINT CHARGE 250.00 ✓
0002 20-00 TUFF COAT ON AFFECTED PARTS. 20.00 ✓
0003 20-22 REMOVE/REFIX REVERSE SENSOR 30.00 ✓

SUB-TOTAL : 650.00

TOTAL : 1,028.60


MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

