



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7464M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FENDER SUB-ASSY FRONT RH	DEFORMED	945.30	945.30
1	EMBLEM SIDE PANEL (HYBRID)	NECESSARY	86.50	86.50
1	COVER OUTER MIRROR RH	TO REPAIR SEE LABOUR	141.90	-
1	MIRROR ASSY OUTER REAR VI	CUT	1,390.10	1,390.10
	LESS 25% DISCOUNT		-640.95	-605.48
			1,922.85	1,816.42
	<u>SPECIAL NETT ITEMS</u>			
1	FRT DOOR L/R CCTPL (SN)	NECESSARY	75.00	75.00
			75.00	75.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF COVER OUTER MIRROR RH.		750.00	525.00
	SPRAYPAINT CHARGE.		800.00	750.00
	CHECK WIRING.		50.00	20.00
			1,600.00	1,295.00
GRAND TOTAL			3,597.85	3,186.42

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,550.00
---	--	--	-----------------

Report Ref No. NS/INC21009233/Vtcn2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.