



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7660M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER COVER	CUT	430.90	430.90
1	RADIATOR GRILLE	SERVICEABLE	1,409.10	-
1	FRONT BUMPER CENTRE MOULDING	SCRATCHED	368.50	368.50
1	FRONT BUMPER GRILLE RH	SCRATCHED	93.45	93.45
1	FRT RH DAY LIGHT	SERVICEABLE	642.50	-
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	588.80	-
1	FRONT FENDER SHIELD	SERVICEABLE	164.70	-
1	FRONT BRACKET SIDE RH	NECESSARY	35.00	35.00
1	FRONT FENDER EMBLEM RH	NECESSARY	26.60	26.60
1	HEAD LAMP RH	SCRATCHED	1,993.65	1,993.65
10	BUMPER CLIP	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-1,155.04	-594.02
			4,620.16	2,376.08
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	NUMBER PLATE W/HOLDER (SN)	SERVICEABLE	55.00	-
			55.00	-
	<b><u>LABOUR</u></b>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		600.00	350.00
	SPRAY PAINT.		600.00	500.00
	RESET FRONT WHEEL ALIGNMENT.		60.00	60.00
	CHECK LIGHTING.		60.00	30.00
			1,320.00	940.00
	<b>GRAND TOTAL</b>		<b>5,995.16</b>	<b>3,316.08</b>

Report Ref No. NS/INC21009234/Vcn2

<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>			<b>3,316.08</b>
--	--	--	-----------------

Report Ref No. NS/INC21009234/Vvcn2



**THEVAN THOMAS KARTHIKESAVAN**



**K.K.LAU CPT(RET)**

**BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE**

**REGD Auto Consultant-SAE, Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.**