

Our Job Ref No 305484958

Date : 02/09/21

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : THEVAN
: SHD4523R

Fax :


DOA: 30/08/2020

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SGX8652G
###
2. The finalized amount shall be:

(a) Spare Parts after List discount		\$0.00
(b) Labour Charges	###	\$560.00
Total for Part-By-Part Repair Cost		\$560.00
(c.) Lumpsum Repair (if applicable)		
Total for Lumpsum repair cost after Less: 20%		
Final Lumpsum Repair cost		
3. Estimated normal period for repairs: 2 working days
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : JUMANI
Tel : 6214 8315
Fax : 65468156

Signature : 
Name : THEVAN
Date : 7/9/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49 / 2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305484958
 REGN NO : SHD4523R
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 18.05.2016
 DATE/TIME IN : 30.08.2021 11:35
 ACCIDENT DATE : 30.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G COVER ASSY-RR BUMPER#	1	1,106.00	20.00	884.80	KV
0002 04-01-0101-0111-G BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	max KV
0003 04-01-0103-0738-G COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	KVC
				SUB-TOTAL	: 1,084.80

JOB NATURE

0000 PB	PANEL BEATING	300.00	280
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 L	REMOVE/REFIX REVERSE SENSOR	80.00	30
		SUB-TOTAL	: 680.00

TOTAL : 1,764.80

MVA NAME & SIGNATURE
 DATE: 31/8/21

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE:

Theran Chh
 theran@lkhauto.com
 82235769
 2 days wp
 31/8/21 1645

Labour only after repair photos

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR ESTIMATE

Time: 13:45:32

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305484958
REGN NO : SHD4523R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 18.05.2016
DATE/TIME IN : 30.08.2021 11:35
ACCIDENT DATE : 30.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION


SUB-TOTAL : 0.00

JOB NATURE

0000 PB	PANEL BEATING	280.00
0001 SP	SPRAYPAINT CHARGE	250.00
0002 L	REMOVE/REFIX REVERSE SENSOR	30.00

SUB-TOTAL : 560.00

TOTAL : 560.00


MWA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE : AUTHORIZED : YES / NO