

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3136Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER COVER	TO REPAIR SEE LABOUR	459.40	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER CENTRE MOULDING ASSY	CUT	451.25	451.25
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	394.80	-
1	FOG LAMP	SERVICEABLE	201.50	-
2	RR BUMPER REINFORCEMENT BRACKET LH/RH @ \$138.10	SERVICEABLE	276.20	-
1	REAR BUMPER LICENCE LAMP	SERVICEABLE	85.30	-
1	REAR BUMPER LOWER MOULDING	CUT	155.00	155.00
	LESS 20% DISCOUNT		-409.09	-125.65
			1,636.36	502.60
	NETT ITEMS			
1	REAR NUMBER PLATE WITH TRIM COVER (N)	CRACKED	45.00	45.00
1	REAR BUMPER REVERSE SENSOR (N)	CUT	180.00	180.00
	LESS 10% DISCOUNT		-	-22.50
			225.00	202.50
	SPECIAL NETT ITEMS			
1	REAR BUMPER RUBBER MAT (SN)	SERVICEABLE	50.00	-
			50.00	-
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER COVER.		700.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	WIRING CHARGE.		50.00	20.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	30.00
			1,130.00	650.00
	GRAND TOTAL		3,041.36	1,355.10

Report Ref No. NS/INC21009236/Vqcn2





Page No.:2 of 2

RECOMMENDED COST OF REPAIRS (CONFIRMED)		1,355.10
---	--	----------

Report Ref No. NS/INC21009236/Vqcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**