

Our Job Ref No : 305484600
Date : 02/09/21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : Mr THEVAN
Vehicle Reg No. : SHA3136Y CTPL

Fax :

27/08/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: NTUC --- SFP 109R
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$705.10
 - (b) Labour Charges \$650.00
 - Total for Part-By-Part Repair Cost** \$1,355.10
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost _____


3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : MS. LOKE YY
Tel : 62148355
Fax : 65468156

Signature : 
Name : Thevan
Date : 7/9/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA3136Y

Date: 28/08/2021

Veh Reg Date: 30.09.2020

Make : HYUNDAI

Insurance: NTUC

Model : IONIQ(G3)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	FOG LAMP			\$201.50
2	RR BUMPER REINFORCEMENT BRACKET LH RH		\$138.10	\$276.20
1	REAR BUMPER LICENCE LAMP			\$85.30
1	REAR BUMPER LOWER MOULDING			\$155.00
	SUB TOTAL			\$2,045.45
	LESS 20%			\$409.09
	DISCOUNTED TOTAL			\$1,636.36
1	REAR BUMPER RUBBER MAT			\$50.00
1	REAR NUMBER PLATE WITH TRIM COVER		-10%	\$45.00
1	REAR BUMPER REVERSE SENSOR		-10%	\$180.00
				\$275.00
	Labour Charge			
	PANEL BEATING			\$700.00
	SPRAY PAINTING CHARGE			\$300.00
	WIRING CHARGE			\$50.00
	REMOVE/REFIX REVERSE SENSOR			\$80.00
	TOTAL LABOUR			\$1,130.00
	ESTIMATE TOTAL			\$3,041.36

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan Lhh
thuan@lhhauto.com
82235769
2dayswp
30/8/21 1745
P/P bfr paint photos

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305484600
 REGN NO : SHA3136Y
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 30.09.2020
 DATE/TIME IN : 27.08.2021 18:30
 ACCIDENT DATE : 27.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00 ✓
0002 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60 ✓
0003 04-01-0104-2545-G	MOULDING-REAR BUMPER LWR	1	155.00	20.00	124.00 ✓
0004 28-01-0104-2029-A	VEHICLE NUMBER PLATE REAR	1	45.00	10.00	40.50 ✓
0005 09-01-9999-0068-A	REVERSE SENSOR ASSY*	1	180.00	10.00	162.00 ✓

SUB-TOTAL : 705.10 ✓

JOB NATURE

0000 PB	PANEL BEATING SHA3136Y	350.00 ✓
0001 SP	SPRAYPAINT CHARGE	250.00 ✓
0002 17-01	CHECK ALL LIGHTING	20.00 ✓
0003 L	REMOVE/REFIX REVERSE SENSOR	30.00 ✓

SUB-TOTAL : 650.00 ✓