



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1094L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER COVER	DEFORMED	1,052.20	1,052.20
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT BUMPER BRACKET TOP RH	NECESSARY	44.80	44.80
1	FRT BUMPER GRILLE RH	SERVICEABLE	187.20	-
1	FRT FENDER RH	DISTORTED	663.00	663.00
1	HEADLAMP RH	CRACKED	1,800.00	1,800.00
1	FRT BUMPER REINFORCEMENT	NOT NECESSARY	588.40	-
1	FRT BUMPER SIDE BRACKET RH	NECESSARY	24.60	24.60
1	HEADLAMP SUPPORT PANEL ASSY	NOT NECESSARY	907.40	-
1	FRT FENDER SHIELD RH	TO REPAIR SEE LABOUR	174.90	-
	LESS 20% DISCOUNT		-1,092.90	-721.32
			4,371.60	2,885.28
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRT FENDER SHIELD RH.		900.00	560.00
	SPRAY PAINTING CHARGE.		850.00	500.00
	TUFF KOTE.		60.00	30.00
	WIRING CHARGE.		60.00	30.00
			1,870.00	1,120.00
	GRAND TOTAL		6,241.60	4,005.28
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,950.00

Report Ref No. NS/INC21009237/Vtcn2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.