

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009240/KVCN2**Date:** 11/10/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00081132000	
Claimant Vehicle No :	SMU5040L	Insured Vehicle No :	GBG6063T	
Date of Loss:	26/08/2021	Nature of Claim:	TP	Claim No: SNM21D204793/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU5040L		Engine No:	2NR5398945
Make & Model:	TOYOTA VIOS, 1.5 E (A)		Chassis No:	MR2B23F3701191490
Reg. Date:	17/08/2020 (Man. Year: 2019)		Odometer:	13848 km
Colour:	Metallic Black			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	420.00	355.00	65.00	15.48
Miscellaneous Items	300.00	300.00	0.00	0.00
Labour	117.60	88.20	29.40	25.00
Paintwork Labour	319.40	319.40	0.00	0.00
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	1,157.00	1,062.60	94.40	8.16
+ GST 7.00/7.00% (\$\$)	80.99	74.38	6.61	8.16
Nett Amount (\$\$)	1,237.99	1,136.98	101.01	8.16

INSPECTION

Date of Assignment:	02/09/2021	Present Location:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected:	07/09/2021	Inspected At:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2021)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU5040L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare Parts		315.00 F	*250.00 F
<u>Supplementary #1</u>						
2	1		*REAR BUMPER SUPPORT	Bent	105.00 F	*105.00 F
F=Franchise part.						
Total Parts (S\$)					420.00	355.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Extra	300.00	300.00
Sub Total (\$\$)			300.00	300.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Including Material	New	319.40	319.40
<u>Labour Items</u>				
2	Total of Labour	New	117.60	88.20
Gross Labour Cost (\$\$)			437.00	407.60

Report was unsubmitted during this print-out.

< END OF ESTIMATES >