

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21009241/ATCE2

Date: 08/12/2021

REFERENCE

Insured/Claimant:	TAN SZE TONG	Policy No:	1800073045-03		
Date of Loss:	01/09/2021	Nature of Claim:	OD	Claim No:	3882058089SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDZ612A		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK058801
Reg. Date:	26/06/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF40JA146757
Colour:	Blue	Odometer:	44902 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$100,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	50,506.00	23,045.76	27,460.24	54.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	24,794.00	16,469.00	8,325.00	33.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	75,300.00	39,514.76	35,785.24	47.52
+ GST 7.00/7.00% (S\$)	5,271.00	2,766.03	2,504.97	47.52
Nett Amount (S\$)	80,571.00	42,280.79	38,290.21	47.52

INSPECTION

Date of Assignment:	02/09/2021		
Date Inspected:	02/09/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	12.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,787.00 FS	*1,429.60 FS
2	1		*FRONT BUMPER FIXING PARTS (NPA)	Not Necessary	0.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Missing	71.00 FS	*56.32 FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	210.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE - RH	Deformed	63.00 FS	*50.08 FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Deformed	365.00 FS	*292.00 FS
7	1		*FRONT BUMPER GUIDE SECTION - RH	Damaged	38.00 FS	*29.84 FS
8	1		*HORN - RH	Not Necessary	126.00 FS	*- FS
9	1		*HORN BRACKET - RH	Not Necessary	29.00 FS	*- FS
10	1		*FRONT FENDER - RH	Distorted	767.00 FS	*613.20 FS
11	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	202.00 FS	*- FS
12	1		*FRONT FENDER CLOSING ELEMENT	Bent	72.00 FS	*57.52 FS
13	1		*FRONT FENDER TOP BRACKET - FRONT RH	Bent	35.00 FS	*27.92 FS
14	1		*FRONT FENDER DEFORMATION BRACKET - RH	Bent	49.00 FS	*39.20 FS
15	1		*RIVET (6PCS)	Necessary	20.00 FS	*15.84 FS
16	1		*FRONT FENDER TOP BRACKET - REAR RH	Bent	32.00 FS	*25.12 FS
17	1		*FRONT FENDER BRACE - RH	Bent	118.00 FS	*94.40 FS
18	1		*FRONT WHEEL HOUSING LINER - RH	Deformed	241.00 FS	*192.80 FS
19	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS (NPA)	Not Necessary	0.00 FS	*- FS
20	1		*FRONT WHEEL SPOILER	Deformed	73.00 FS	*58.40 FS
21	1		*FRONT WHEEL SPOILER TRIM - RH	Deformed	36.00 FS	*28.56 FS
22	1		*FRONT FENDER STONE CHIP GUARD - RH	Necessary	51.00 FS	*40.32 FS
23	1		*FRONT FENDER TOP COVER - RH	Deformed	31.00 FS	*24.64 FS
24	1		*FRONT HEADLIGHT CORNER COVER - RH	Deformed	23.00 FS	*17.92 FS
25	1		*BONNET	Dented	3,246.00 FS	*2,596.80 FS
26	1		*BONNET ATTACHMENT PARTS	Not Necessary	412.00 FS	*- FS
27	2		*BONNET HINGE - LH / RH	Not Necessary	610.00 FS	*- FS
28	1		*BONNET IMPACT PROTECTOR - LH / RH / CENTER	Necessary	84.00 FS	*65.68 FS
29	1		*BONNET STRIKER	Not Necessary	50.00 FS	*- FS
30	1		*BONNET LOCK	Not Necessary	214.00 FS	*- FS
31	1		*HEADLIGHT - RH	Cracked	7,693.00 FS	*6,154.40 FS
32	1		*HEADLIGHT LIFT CYLINDER - RH	Not Necessary	210.00 FS	*- FS
33	1		*HEADLIGHT LIFT CYLINDER HOSE	Not Necessary	93.00 FS	*- FS
34	1		*LOCK CARRIER	Cracked	1,016.00 FS	*812.80 FS
35	6		*COOLANT	Necessary	266.00 FS	*212.64 FS
36	2		*FRONT FENDER CONNECTING PLATE - RH	Not Necessary	217.00 FS	*- FS
37	1		*WATER RESERVOIR	Not Necessary	251.00 FS	*- FS
38	1		*FRONT WINDSCREEN	Cracked	1,125.00 FS	*900.00 FS
39	1		*FRONT WINDSCREEN FOIL	Necessary	147.00 FS	*109.20 FS
40	1		*FRONT WINDSCREEN RETAINING SPRING	Necessary	137.00 FS	*16.56 FS
41	1		*FRONT WINDSCREEN SPRING CLIP	Necessary	21.00 FS	*16.56 FS
42	1		*PRIMER	Necessary	20.00 FS	*15.76 FS
43	1		*FRONT DOOR - RH	Dented	3,192.00 FS	*2,553.60 FS
44	1		*FRONT DOOR OUTER SEAL - R	Necessary	205.00 FS	*164.00 FS
45	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
46	1		*CLEAING SOLUTION	Not Necessary	68.00 FS	*- FS
47	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
48	1		*BUNGS	Not Necessary	4.00 FS	*- FS
49	1		*FRONT DOOR ATTACHMENT PARTS (NPA)	Not Necessary	0.00 FS	*- FS
50	1		*FRONT DOOR CATCH - RH	Not Necessary	105.00 FS	*- FS
51	1		*TYRE PRESSURE STICKER	Necessary	38.00 FS	*29.84 FS
52	1		*FRONT WINDOW REGULATOR - RH	Not Necessary	282.00 FS	*- FS
53	1		*FRONT WINDOW REGULATOR MOTOR - RH	Not Necessary	313.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
54	1	*REAR VIEW MIRROR	Not Necessary	1,079.00 FS	*- FS
55	1	*REAR VIEW MIRROR TOP COVER	Not Necessary	32.00 FS	*- FS
56	1	*FRONT MIRROR MOUNTING - RH	Not Necessary	897.00 FS	*- FS
57	1	*FRONT RIM - RH	Cut	1,690.00 FS	*1,352.00 FS
58	1	*FRONT SUB FRAME	Not Necessary	1,891.00 FS	*- FS
59	1	*FRONT WISHBOON LINK - RH	Bent	539.00 FS	*430.80 FS
60	1	*FRONT SUSPENSION GUIDE - RH	Bent	943.00 FS	*754.40 FS
61	2	*FRONT UPPER ARM - RH	Bent	1,024.00 FS	*818.40 FS
62	1	*FRONT WHEEL BEARING HOUSING - RH	Damaged	968.00 FS	*774.00 FS
63	1	*FRONT SWIVEL JOINT - RH	Bent	193.00 FS	*154.40 FS
64	1	*FRONT WHEEL HUB - RH	Damaged	479.00 FS	*383.20 FS
65	1	*FRONT WHEEL BEARING - RH	Damaged	246.00 FS	*196.80 FS
66	1	*FRONT SUSPENSION FORKS - RH	Not Necessary	264.00 FS	*- FS
67	1	*FRONT COUPLING ROD - RH	Not Necessary	127.00 FS	*- FS
68	1	*FRONT ANTI ROLL BAR	Not Necessary	433.00 FS	*- FS
69	1	*FRONT DRIVE SHAFT - RH	Not Necessary	2,650.00 FS	*- FS
70	1	*FRONT SHOCK ABSORBER - RH	Bent	301.00 FS	*240.40 FS
71	1	*FRONT STEERING RACK	Not Necessary	6,787.00 FS	*- FS
72	1	*FRONT TRACK ROD - RH	Bent	99.00 FS	*78.88 FS
73	1	*FRONT TIE ROD END - RH	Bent	197.00 FS	*157.20 FS
74	1	*FRONT LOWER NOISE INSULATION	Not Necessary	572.00 FS	*- FS
75	1	*FRONT DOOR WINDOW CHROME SLOT SEAL - RH	Not Necessary	307.00 FS	*- FS
76	1	*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
77	1	*CRAVITY WAX	Not Necessary	140.00 FS	*- FS
78	1	*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
79	1	*STONE CHIPS	Not Necessary	180.00 FS	*- FS
80	1	*FRONT WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
81	1	*SUNDRIES	Necessary	500.00 FS	*362.96 FS
82	1	*HEADLIGHT WASHER PIPE (Supplementary)	Cut	39.00 F	*30.80 F
83	1	*FRONT TYRE- RHS (Supplementary)	Torn	370.00 F	*370.00 F
84	1	*SUSPENSION STRUT DOME - RH (Supplementary)	Not Necessary	1,912.00 F	*- F
85	1	*SUSPENSION CONSOLE - RH (Supplementary)	Not Necessary	472.00 F	*- F

F=Franchise part. S=SpcNett.

Total Parts (S\$)	50,506.00	23,045.76
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
4	TO RENEW FRONT WINDSCREEN	New	480.00	480.00
5	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN	New	400.00	400.00
6	TO RENEW FRONT WINDSCREEN SENSOR FOIL AND RESET SYSTEM	New	300.00	300.00
7	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN	New	200.00	150.00
8	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,400.00	2,400.00
9	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	350.00	280.00
10	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER, RHS FRONT DOOR AND RHS FRONT DOOR AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS FRONT TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	8,050.00	3,750.00
11	TO RESPRAY FRONT BUMPER, BONNET, HINGES, RHS FRONT FENDER, RHS FRONT FENDER TOP SUPPORT, RHS FRONT DOOR, RHS WING MIRROR COVER AND RHS A-PILLAR	New	6,000.00	2,475.00
12	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	520.00
13	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
14	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER	New	800.00	800.00
15	TO PLACE THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR	New	2,400.00	2,400.00
16	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			24,794.00	16,469.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >