

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009242/KQCN2**Date:** 05/10/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00082372102

Claimant Vehicle No : SKM5066D **Insured Vehicle No :** GX5846J

Date of Loss: 30/08/2021 Nature of Claim: TP Claim No: SNM21D204883/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKM5066D**

Make & Model: HONDA ODYSSEY, 2.4 (A) Engine No: K24Z21300726

Reg. Date: 08/10/2009 (Man. Year: 2009) Chassis No: JHMRB38509C200721

Colour: Metallic Black Odometer: 230706 km

Engine Capacity: 2354 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55ZR17 Rear Tyre Size: 215/55ZR17

Front Left Side: Tourador 7 mm Rear Left Side: Tourador 7 mm

Front Right Side: Tourador 7 mm Rear Right Side: Tourador 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,874.00	2,495.20	1,378.80	35.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,920.00	1,620.00	300.00	15.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,794.00	4,115.20	1,678.80	28.97
Approved Total (Overridden) (S\$)		4,100.00		
(S\$)	5,794.00	4,100.00	1,694.00	29.24
+ GST 7.00/7.00% (S\$)	405.58	287.00	118.58	29.24
Nett Amount (S\$)	6,199.58	4,387.00	1,812.58	29.24

INSPECTION

Date of Assignment: 13/09/2021 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 06/09/2021 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Oct 2021)
Parts:	M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKM5066D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC FRT BUMPER	Buckled/Mtg Cracked	480.00 F	*480.00 FL
2	1		*1 PC FRT BUMPER LH SIDE RETAINER	Distorted	12.00 F	*12.00 FL
3	1		*1 PC FRT BUMPER REINFORCEMENT	Repair	195.00 F	*- FL
4	1		*1 PC FRT BUMPER LOWER SKIRT	Buckled/Cut	180.00 F	*180.00 FL
5	1		*1 PC FRT BUMPER LH FOG LAMP	Serviceable	210.00 F	*- FL
6	1		*6 PCS FRT BUMPER CLIPS @2/PC	Necessary	12.00 F	*12.00 FL
7	1		*1 PC FRT LH FENDER	Bent	370.00 F	*370.00 FL
8	1		*1 PC FRT LH FENDER INNER SHIELD	Cracked	75.00 F	*75.00 FL
9	1		*1 PC FRT LH HEADLAMP	Cut	490.00 F	*490.00 FL
10	1		*1 PC FRT LH HEADLAMP LOWER GARNISH	Cracked	35.00 F	*35.00 FL
11	1		*1 PC FRT LH SIDE MIRROR ASSY	Cracked	345.00 F	*345.00 FL
12	1		*1 PC FRT LH SIDE MIRROR COVER	Cracked	70.00 F	*70.00 FL
13	1		*1 PC FRT LH SPORT RIM (GEN)	Dented	580.00 F	*580.00 FL
14	1		*1 PC FRT LH SHOCK ABSORBER	Serviceable	200.00 F	*- FL
15	1		*1 PC FRT LH KNUCKLE ARM	Bent	245.00 F	*245.00 FL
16	1		*1 PC FRT LH WHEEL BEARING	Necessary	95.00 F	*95.00 FL
17	1		*1 PC FRT LH PARKING SENSOR	Serviceable	150.00 F	*- FL
Supplementary #1						
18	1		*1 PC AIR FILTER RESONATOR	Cracked	130.00 F	*130.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	3,874.00	3,119.00
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	623.80
Total Parts (\$)	3,874.00	2,495.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT BUMPER ASSY,HEADLAMP,FRT LH FENDER,SIDE MIRROR,TO KNOCK & REPAIR FRT LH FENDER INNER PANEL,FRT LH DOOR & REALIGN THE SAME	New	700.00	560.00
2	PUTTY & RESPRAY FRT BUMPER,REINFORCEMENT,FRT LH FENDER,FRT LH FENDER INNER PANEL,FRT LH DOOR,FRT LH SIDE MIRROR COVER,LOWER SKIRT	New	950.00	850.00
3	REMOVE & REFIX FRT LH UNDER CARRIAGE,CHECK DRIVE SHAFT & STEERING	New	180.00	120.00
4	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
5	RUSTPROOFING	New	30.00	30.00
Gross Labour Cost (\$\$)			1,920.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >