

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

Page No.:1 of 1

	FRE-REFAIR INSPECTION REFORT					
	MS FIRST CAPITA	L INSURANCE LTD	R	Ref:	CS3/FCI21009247/Vvf3e2	
	36 ROBINSON RO SINGAPORE 0688	D	Date:	13/09/2021		
			C	Code:	FCI2	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	YQ 2237K	Veh. Inspected		PC 7969D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	D21002474MFCV	Excess (\$)		0.00	
	Assign From	RACHELWU LIMEI	Assign Date		02/09/2021	
2. Vehicle Particulars & Condition						
	Make & Model	MERCEDES BENZ V220	c.c		2143	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	WDF44781523538311	Colour		BLACK	
	Odometer	80415 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/55Z R17	APSEN		6 mm	
	L/H Front Tyre	225/55Z R17	APSEN		6 mm	
	R/H Rear Tyre	225/55Z R17	APSEN		6 mm	
	L/H Rear Tyre	225/55Z R17	APSEN		6 mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.		BODY.			
5.	General Information					
	Accident Date	31/08/2021	Inspect Date / Ti	me	03/09/2021 ( 01:00 PM )	
	Survey held at	2 KAKI BUKIT AVE 22 #01-11 KAKI BUKIIT AUTOHUB				
	Repairer	BEST AUTO K PTE LTD				
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$91,000.00					

Report Ref No. CS3/FCI21009247/Vvf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser