

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009249/KEA3Q2**Date:** 14/12/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800091037
Claimant Vehicle No :	SJU1571H	Insured Vehicle No :	SMC9656D
Date of Loss:	31/08/2021	Nature of Claim:	TP
		Claim No:	3086737019SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU1571H	Engine No:	3ZZ4943009
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106158686
Reg. Date:	20/11/2009 (Man. Year: 2009)	Odometer:	193311 km
Colour:	Metallic Gold		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,947.80	3,036.40	3,911.40	56.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,520.00	1,820.00	700.00	27.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,467.80	4,856.40	4,611.40	48.71
Approved Total (Overridden) (S\$)		3,850.00		
(S\$)	9,467.80	3,850.00	5,617.80	59.34
+ GST 7.00/7.00% (S\$)	662.75	269.50	393.25	59.34
Nett Amount (S\$)	10,130.55	4,119.50	6,011.05	59.34
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
Nett Liability (S\$)		4,599.50		

INSPECTION

Date of Assignment:	02/09/2021	
Date Inspected:	06/09/2021	Inspected At: Ricardo Auto Centre Pte Ltd (HQ) 160 Sin Ming Drive, #02-02, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	7.0 days	

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	612.00 F	*466.20 FL
2	1		*REAR BUMPER SPONGE	Serviceable	126.50 F	*- FL
3	1		*REAR BUMPER RETAINER LH & RH (LONG)	N/S Distorted	145.80 F	*72.90 FL
4	1		*REAR BUMPER RETAINER LH & RH (SHORT)	N/S Distorted	69.40 F	*34.70 FL
5	10		*REAR BUMPER CLIPS	Necessary	35.00 F	*35.00 FL
6	1		*REAR BUMPER RETAINER UPPER LH	Serviceable	66.30 F	*- FL
7	1		*REAR FENDER LH	Buckled	1,682.80 F	*1,219.10 FL
8	1		*REAR FENDER LAMP LH	Broken	473.60 F	*414.10 FL
9	1		*REAR BUMPER REFLECTOR LH	Serviceable	44.30 F	*- FL
10	1		*BOOT WEATHERSTRIP	Distorted / Dented	194.20 F	*194.20 FL
11	1		*BOOT EMBLEM -COROLLA /ALTIS	Necessary	108.20 F	*48.20 FL
12	1		*BOOT EMBLEM -TOYOTA LOGO	Necessary	80.00 F	*68.00 FL
13	1		*BOOT EMBLEM -1.6	Necessary	35.80 F	*35.80 FL
14	1		*PLATE -ELEGANCE	Necessary	35.80 F	*35.80 FL
15	1		*REAR END PANEL	Bent	670.00 F	*562.10 FL
16	1		*REAR END PANEL PLATE	Serviceable	213.80 F	*- FL
17	1		*BOOT LAMP LH	Serviceable	245.60 F	*- FL
18	1		*BOOT LOCK	Repair	111.80 F	*- FL
19	1		*COVER ,LUGGAGE COMPARTMENT TRIM LH	Deformed	390.30 F	*329.10 FL
20	1		*SET REAR BUMPER SENSOR	Scratched	220.00 FS	*200.00 FS
21	1		*BOOT LID (LOCAL REPAIR)	Dented	1,386.60 FS	*200.00 FS
					Sub Total (\$\$)	6,947.80 3,915.20
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00 878.80
					Total Parts (\$\$)	6,947.80 3,036.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT ,WELD & STRAIGHTEN REAR PORTION OF CAR CAUSED BY ACCIDENT ,ADJUST & REPLACE DAMAGE PARTS	New	1,000.00	900.00
2	TO REMOVE FUEL TANK ENABLE TO REMOVE & REPLACE LH REAR FENDER	New	200.00	60.00
3	TO COMPUTERISE WHEEL ALIGNMENT	New	60.00	0.00
4	TO TUFF COAT REPAIRED AREAS	New	60.00	60.00
5	TO SPRAY PAINT ON REPAIRED AREAS	New	1,200.00	800.00
Gross Labour Cost (\$)			2,520.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >