



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. CB 6846R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT LH HEADLAMP	CRACKED	1,350.00	1,350.00
1	FRONT PANEL	TO REPAIR SEE LABOUR	2,200.00	-
1	FRONT LH BUMPER BRACKET	DISTORTED	355.00	355.00
1	FRONT BUMPER	BENT	1,280.00	1,280.00
	LESS 10% DISCOUNT		-	-298.50
			5,185.00	2,686.50
<b><u>SPECIAL NETT ITEMS</u></b>				
3	SEALANT @\$40.00 (SN)	NOT NECESSARY	120.00	-
1	IU UNIT (SN)	NOT NECESSARY	26.00	-
1	SCHOOL BUS STICKER (SN)	NECESSARY	15.00	15.00
			161.00	15.00
<b><u>LABOUR</u></b>				
	REMOVE & REFIT FRONT WINDSCREEN TO ASSIST REPAIR.	NOT NECESSARY	200.00	-
	CHECK WIRING.		30.00	20.00
	REMOVE & REFIT LH SIDE GLASS TO ASSIST REPAIR.	NOT NECESSARY	100.00	-
	SPRAY PAINTING WITH DESIGN.		1,600.00	1,180.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF FRONT PANEL.		1,200.00	600.00
			3,130.00	1,800.00
<b>GRAND TOTAL</b>			<b>8,476.00</b>	<b>4,501.50</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,600.00</b>

Report Ref No. CS/SMO21009255/Kqf3n2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.