



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FJ 53Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	HANDLERBARS LH & RH @\$100.00	BENT	200.00	200.00
2	HANDLEBAR GRIPS LH & RH @\$20.00	NOT NECESSARY	40.00	-
2	HANDLEBAR BALANCERS LH & RH @\$25.00	O/S CUT	50.00	25.00
2	HANDLEBAR SIDE MIRRORS LH & RH @\$40.00	O/S CUT	80.00	40.00
1	HANDLEBAR LH CLUTCH LEVER	NOT NECESSARY	50.00	-
1	HANDLEBAR RH FRONT BRAKE LEVER	CUT	50.00	50.00
1	HEADLAMP ASSEMBLY	CRACKED	220.00	220.00
1	HEADLAMP FAIRING	CUT	160.00	160.00
1	HEADLAMP FAIRING VISOR	CRACKED	85.00	85.00
2	FRONT SIGNAL LAMPS LH & RH @\$60.00	N/S CRACKED / O/S CUT	120.00	80.00
1	SPEEDOMETER & RPM METER	CUT	460.00	460.00
2	FRONT FORKS @\$340.00	BENT	680.00	680.00
2	SETS FRONT FORK STEM BEARINGS @\$90.00	NECESSARY	180.00	180.00
1	FRONT FORK UPPER BRACKET (TRIPLE PLATE)	BENT	120.00	120.00
1	FRONT FORK LOWER BRACKET (TRIPLE PLATE)	BENT	120.00	120.00
1	FRONT STEM STAY ASSEMBLY	BENT	220.00	220.00
1	FRONT RIM - CHROME	BENT	350.00	280.00
1	SET FRONT RIM BEARINGS	NOT NECESSARY	80.00	-
1	FRONT RIM SLIDER (LONG BOLT)	NOT NECESSARY	40.00	-
1	FRONT RIM SLIDER NUT	CUT	5.00	5.00
1	FUEL TANK CASING	NOT NECESSARY	480.00	-
1	CENTRE SIDE FAIRINGS (RXZ) RH	NOT NECESSARY	100.00	-
1	REAR TAIL FAIRING	NOT NECESSARY	145.00	-
1	REAR TAIL FAIRING HANDLEBAR	NOT NECESSARY	70.00	-
1	REAR TAIL FAIRING SIGNAL LAMPS	NOT NECESSARY	60.00	-
1	REAR TAIL FAIRING BRAKE LAMP	NOT NECESSARY	80.00	-
1	KICK-START PADEL	NOT NECESSARY	65.00	-
1	RIDER FOOTREST - RH	CUT	45.00	45.00
1	PILLION FOOTREST - RH	CUT	45.00	45.00
1	FOOTREST BRACKET ASSEMBLY - RH	NOT NECESSARY	165.00	-

Report Ref No. CS/AGI21009256/Aqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SIDE STAND	NOT NECESSARY	80.00	-
1	MAIN STAND	NOT NECESSARY	110.00	-
1	EXHAUST ASSEMBLY	NOT NECESSARY	600.00	-
1	EXHAUST MID PIPE - SIDE PROTECTOR	CUT	90.00	90.00
1	EXHAUST REAR MUFFLER - SIDE PROTECTOR COVER	CUT	90.00	90.00
1	EXHAUST GASKET	NOT NECESSARY	40.00	-
	LESS 10% DISCOUNT		-557.50	-319.50
			5,017.50	2,875.50
	<u>SPECIAL NETT ITEMS</u>			
1	HANDLEBAR RH BREMBO RCS 15 BRAKE MASTER CYLINDER (SN)	LEAKING	500.00	400.00
1	HANDLEBAR RH RIZOMA BRAKE RESERVOIR AND BRACKET (SN)	NOT NECESSARY	250.00	-
1	FRONT NUMBER PLATE (SN)	BENT	30.00	20.00
1	FRONT FENDER / MUDGUARD - APRILIA RS125 (SN)	DEFORMED	280.00	200.00
1	FRONT TYRE (SN)	NOT NECESSARY	180.00	-
2	REAR SUSPENSIONS - KONI BRAND @\$550.00 (SN)	NOT NECESSARY	1,100.00	-
1	FRONT BRAKE DISC - ENLARGED SIZE (SN)	NOT NECESSARY	280.00	-
			2,620.00	620.00
	<u>LABOUR</u>			
	LABOUR CHARGE.		400.00	250.00
	SPRAY PAINT AND MISC STICKERS.		200.00	180.00
	RELEASE & RENEW - BRAKE FLUID BLEEDING.		100.00	40.00
	CHASSIS ALIGNMENT - FRONT.	NOT NECESSARY	250.00	-
			950.00	470.00
GRAND TOTAL			8,587.50	3,965.50

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,100.00
---	--	--	-----------------

Report Ref No. CS/AGI21009256/Aqy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.