

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009257/AEA3Q2**Date:** 14/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993731
Claimant Vehicle No :	SKL251Z	Insured Vehicle No :	GW2418L
Date of Loss:	29/08/2021	Nature of Claim:	TP
		Claim No:	9585570451SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL251Z	Engine No:	ZY518812
Make & Model:	MAZDA 2, 1.5 (A)	Chassis No:	JM0DE10Y190130184
Reg. Date:	02/02/2009 (Man. Year: 2008)	Odometer:	187243 km
Colour:	Red		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/45 R15	Rear Tyre Size:	195/45 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,656.04	933.08	722.96	43.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,040.00	430.00	610.00	58.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,696.04	1,363.08	1,332.96	49.44
Approved Total (Overridden) (S\$)		1,100.00		
(S\$)	2,696.04	1,100.00	1,596.04	59.20
+ GST 7.00/7.00% (S\$)	188.72	77.00	111.72	59.20
Nett Amount (S\$)	2,884.76	1,177.00	1,707.76	59.20
+ Car Rental (2.0 x S\$90.00/day + 7.00% GST) (S\$)		192.60		
		1,369.60		
		Nett Liability (S\$)		

INSPECTION

Date of Assignment:	02/09/2021	
Date Inspected:	07/09/2021 Inspected At:	Auto N Cars Services Pte Ltd (HQ) Blk 1 Kaki Bukit Ave 6 #01-04, AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	2.0 days	

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	904.40 FL	*798.00 FL
2	8		*FRONT BUMPER CLIPS	Necessary	64.00 FL	*30.00 FL
3	1		*FRONT BUMPER NUMBER PLATE GARNISH	Cut	307.10 FL	*307.10 FL
4	1		*FRONT GRILLE	Not Necessary	139.10 FL	*- FL
5	1		*FRONT GRILLE EMBLEM	Not Necessary	574.20 FL	*- FL
6	1		*FRONT NUMBER PLATE	Dented	25.00 FS	*25.00 FS
7	1		*SUNDRIES	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,053.80	1,160.10
- List Item Discount on L Items 20.00/20.00% (\$)	397.76	227.02
Total Parts (\$)	1,656.04	933.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK & STRAIGHTEN THE DAMAGED PANELS ,REMOVE & RENEW DAMAGED PARTS ,ADJUST & REALIGN THE SAME	New	480.00	200.00
2	TO CHECK ALL WIRING AND LIGHTING	New	80.00	30.00
3	TO SPRAY PAINT ALL AFFECTED AREAS	New	480.00	200.00
			Gross Labour Cost (\$)	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >