

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009259/VGA3Q2
Date: 07/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100510018
Claimant Vehicle No :	SHA1049D	Insured Vehicle No :	SLN8956Z
Date of Loss:	01/09/2021	Nature of Claim:	TP
		Claim No:	2191306611SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA1049D	Engine No:	D4FDEU497261
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU090133
Reg. Date:	09/06/2016 (Man. Year: 2016)	Odometer:	726809 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	206/60 R16	Rear Tyre Size:	206/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,527.18	6,807.82	6,719.36	49.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,920.00	1,730.00	1,190.00	40.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,447.18	8,537.82	7,909.36	48.09
Approved Total (Overridden) (S\$)		6,850.00		

(S\$)	16,447.18	6,850.00	9,597.18	58.35
+ GST 7.00/7.00% (S\$)	1,151.30	479.50	671.80	58.35
Nett Amount (S\$)	17,598.48	7,329.50	10,268.98	58.35
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$110.67/day) (S\$)		553.35		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,134.85		
Global Sum Settlement (S\$)		8,000.00		

INSPECTION

Date of Assignment: 02/09/2021

Date Inspected: 02/09/2021

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Estimated Period of Repair: 4.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Deformed	2,265.90 FL	*2,265.90 FL
2	2		*BONNET HINGE (LH/RH)	Serviceable	253.40 FL	*- FL
3	1		*BONNET LOCK	Serviceable	142.20 FL	*- FL
4	1		*RADIATOR GRILLE H EMBLEM	Cut	129.50 FL	*129.50 FL
5	1		*RADIATOR GRILLE	Cut	1,480.00 FL	*1,480.00 FL
6	1		*FRONT BUMPER	Deformed	1,052.20 FL	*1,052.20 FL
7	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
8	1		*FRONT BUMPER SPONGE	Cut	379.20 FL	*379.20 FL
9	1		*FRONT BUMPER REINFORCEMENT	Dented	588.40 FL	*588.40 FL
10	1		*FRONT BUMPER CENTRE GRILLE	Cut	114.00 FL	*114.00 FL
11	1		*FRONT BUMPER LIP	Not Necessary	152.00 FL	*- FL
12	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Serviceable	44.80 FL	*- FL
13	2		*FRONT BUMPER BRACKET (LH/RH)	Necessary	49.20 FL	*49.20 FL
14	1		*HEADLAMP SUPPORT PANEL ASSY	Serviceable	907.40 FL	*- FL
15	1		*HEADLAMP (LH/RH)	O/S Damaged	2,776.00 FL	*1,388.00 FL
16	1		*HEADLAMP SUPPORT TOP COVER	Serviceable	222.60 FL	*- FL
17	1		*RADIATOR	Serviceable	1,637.20 FL	*- FL
18	1		*RADIATOR FAN /COWLING	Serviceable	1,194.20 FL	*- FL
19	2		*RADIATOR GIARD	Serviceable	153.00 FL	*- FL
20	2		*HORN UNIT (LH/RH)	Serviceable	147.60 FL	*- FL
21	1		*HORN WIRE	Serviceable	156.60 FL	*- FL
22	1		*AIRCON CONDENSER	Serviceable	947.80 FL	*- FL
23	1		*AIRCON SUCTION & LIQUID HOSE	Serviceable	624.00 FL	*- FL
24	1		*REAR BUMPER	Cut	553.00 FL	*553.00 FL
25	1		*REAR BUMPER UNDER COVER	Cut	228.00 FL	*228.00 FL
26	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
27	1		*REAR BUMPER REINFORCEMENT	Serviceable	428.40 FL	*- FL
28	1		*FRONT NO PLATE WITH TRIM COVER	Cracked	55.00 FS	*55.00 FS
29	1		*REVERSE SENSORS	Cut	135.70 FS	*135.70 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,861.30	8,462.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,334.12	1,654.28
Total Parts (\$\$)	13,527.18	6,807.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	840.00
2	SPRAY PAINTING CHARGE	New	1,200.00	750.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	50.00	20.00
5	TOWING CHARGE	New	60.00	60.00
6	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
7	REMOVE /REFIX RADIATOR	New	90.00	0.00
8	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	0.00
Gross Labour Cost (S\$)			2,920.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >