

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009263/AYA3Q2**Date:** 18/02/2023**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : YP4651P**Insured Vehicle No :** GBK7416G

Date of Loss: 30/08/2021

Nature of Claim: TP

Claim No: 1895672121SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **YP4651P**

Make & Model: ISUZU NPR85UH5A, 3.0 D (M)

Engine No: 4JJ12T7013

Reg. Date: 18/11/2016 (Man. Year: 2016)

Chassis No: JAANPR85HG7100579

Colour: Blue

Odometer: 151056 km

Engine Capacity: 2999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 7.00 R16

Rear Tyre Size: 195/85 R16

Front Left Side: West Lake 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,916.00	6,256.25	8,659.75	58.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,100.00	2,040.00	2,060.00	50.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,016.00	8,296.25	10,719.75	56.37
Approved Total (Overridden) (S\$)		6,600.00		
Nett Amount (S\$)	19,016.00	6,600.00	12,416.00	65.29
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,307.45		

INSPECTION

Date of Assignment: 02/09/2021

Date Inspected: 03/09/2021 Inspected At:

Ace Autolution Pte Ltd (KAKI BUKIT)

13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre

Singapore 417807

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Bent	30.00 FS	*30.00 FS
2	1		*FRONT NUMBER PLATE HOLDER	Deformed	50.00 FS	*50.00 FS
3	1		*FRONT BUMPER	Bent	1,500.00 FS	*1,400.00 FS
4	1		*FRONT BUMPER LAMP	O/S Cracked	370.00 F	*185.00 FL
5	2		*FRONT BUMPER BRACKET	Bent	302.00 F	*302.00 FL
6	1		*FRONT GRILLE	Cracked	435.00 F	*435.00 FL
7	1		*FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
8	1		*FRONT SIGNAL LAMP	O/S Cracked	410.00 F	*205.00 FL
9	1		*FRONT SIGNAL LAMP CHROME COVER	O/S Necessary	360.00 FS	*200.00 FS
10	2		*HEADLAMP	Not Necessary	882.00 F	*- FL
11	1		*HEADLAMP CHROME COVER	Not Necessary	400.00 FS	*- FS
12	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
13	1		*REAR NUMBER PLATE LAMP	Not Necessary	67.00 F	*- FL
14	1		*REAR NUMBER PLATE BRACKET	Bent	116.00 F	*116.00 FL
15	1		*REAR BUMPER	Bent	1,200.00 FS	*1,000.00 FS
16	1		*TAILLAMP	O/S Cracked	564.00 F	*282.00 FL
17	1		*REAR STEP WOODEN BEAM	Cracked	380.00 FS	*300.00 FS
18	1		*REAR BOX LOWER WOODEN BEAM	Cracked	850.00 FS	*750.00 FS
19	1		*REAR BOX LOWER FRAME	Dented	900.00 FS	*800.00 FS
20	1		*REAR LH DOOR	Not Necessary	2,200.00 FS	*- FS
21	1		*REAR LH DOOR LOCK BEAM	Not Necessary	400.00 FS	*- FS
22	1		*REAR LH DOOR LOCK CATCH	Not Necessary	200.00 FS	*- FS
23	1		*REAR RH DOOR	Not Necessary	2,200.00 FS	*- FS
24	1		*REAR RH DOOR LOCK BEAM	Not Necessary	400.00 FS	*- FS
25	1		*REAR RH DOOR LOCK CATCH	Not Necessary	200.00 FS	*- FS
26	1		*REAR CAMERA	Damaged	450.00 FS	*380.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,916.00	6,485.00
- List Item Discount on L Items 0.00/15.00% (\$\$)	0.00	228.75
Total Parts (\$\$)	14,916.00	6,256.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	900.00
2	SPRAY PAINTING	New	1,200.00	400.00
3	WIRING	New	100.00	60.00
4	TO SPRAY TUFF COAT	New	150.00	50.00
5	TO REMOVE REAR CAMERA	New	100.00	50.00
6	TO VARNISH WOODEN MEMBERS	New	150.00	80.00
7	TO LIFT REAR STORAGE BOX TO FACILITATE REPAIRS	New	1,000.00	500.00
Gross Labour Cost (\$\$)			4,100.00	2,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >