

YP4651P. 2016 Nov
Isuzu NPH85 2999cc.
JAANPR85H 67100579.

2021 Sept
TP AIG.
Xiao Tong.

Front Number Plate.	Bent	30(SN) ✓
Front Number Plate Holder.	Rhd	50(SN) ✓
Front Bumper	Bent	2000(SN) 1400(SN)
Front Bumper Lamp x02	RH could	$185 \times 2 = 370$ 185
Front Bumper Bracket x02	Bent	$156 \times 2 = 302$
Front Grille	could	435 ✓
Front Grille Lips.	new	20(SN) ✓
Front Signal Lamp x02	RH could	$205 \times 1 = 410$ 205
Front Signal Lamp Chrome Cover x02.	RH new	$180 \times 2 = 360$ 200(SN)
Headlamp x02	NP new	$442 \times 2 = 882$ X
Headlamp Chrome Cover x02	NP new	$300 \times 2 = 600$ 400(SN) X

P①

XP 4651P.

Reer Number Plate.	Bert	30(SN).	✓
Reer Number Plate Lamp.	Man	67	+
Reer Number Plate Bracket.	Bert	116	✓
Reer Bumper.	Bert	1200(SN) 1000(SN)	
Taillamp x 02.	Culld RH	282 x 2 = 564	282
Reer Step Wooden Beam.	Culld	380(SN) 300(SN)	
Reer Box Lower Wooden Beam.	Culld	850(SN) 750(SN)	
Reer Box Lower Frame.	Dented	900(SN) 800(SN).	
Reer LH Door	}	2200(SN).	+
Reer LH Door Lock Beam.		400(SN)	+
Reer LH Door Lock Catch.		200(SN)	+
Reer RH Door		2200(SN)	+
Reer RH Door Lock Beam.		400(SN)	+
Reer RH Door Lock Catch.		200(SN)	+

P(2)

YP 4651P

Rear Camera. ~~Ind~~

~~450(SN)~~ 380(SN).

Panel Beating	1400	900
Spry Painting.	1200	400
Wiring.	100	60
To spray tuff coat.	150	50
To remove rear camera.	100	50.
To varnish wooden members	150	80.
To lift rear Storage Box to facilitate repairs.	1000	500.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

List: 1525

Len 15%: 1296.25

S.N: 4960

Labour: 2040

total: 8296.25

M/S: 66K ✓

07 Days.

P (3)