

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21009266/AQCE2

Date: 15/11/2021

REFERENCE

Insured/Claimant: AW SIN HUI Policy No: 1800001701
Date of Loss: 28/08/2021 Nature of Claim: OD Claim No: 4927756791SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV6417J**
Make & Model: AUDI A3, 999cc TFSI S TRONIC (LED) (A) Engine No: CHZ592063
Reg. Date: 08/01/2018 (Man. Year: 2017) Chassis No: WAUZZZ8V3J1030068
Colour: Grey Odometer: 55676 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$85,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,734.00	10,720.96	7,013.04	39.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,702.00	2,542.00	4,160.00	62.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,436.00	13,262.96	11,173.04	45.72
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	24,136.00	12,962.96	11,173.04	46.29
+ GST 7.00/7.00% (S\$)	1,689.52	907.41	782.11	46.29
Nett Amount (S\$)	25,825.52	13,870.37	11,955.15	46.29

INSPECTION

Date of Assignment: 02/09/2021
Date Inspected: 02/09/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,987.00 FS	*1,589.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	39.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	160.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	536.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	297.00 FS	*- FS
7	1		*FRONT BUMPER COVER TRIM - LH	Not Necessary	163.00 FS	*- FS
8	1		*FRONT WHEEL HOUSING LINER ADAPTER - LH	Not Necessary	38.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,406.00 FS	*1,124.80 FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Cracked	191.00 FS	*152.40 FS
11	1		*FRONT BUMPER AIR GRILLE - LH	Not Necessary	188.00 FS	*- FS
12	1		*AIR CONDITIONER STICKER	Necessary	8.00 FS	*5.68 FS
13	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
14	1		*FRONT BUMPER REINFORCEMENT	Dented	795.00 FS	*636.00 FS
15	1		*FRONT BUMPER REINFORCEMENT FOAM	Cracked	189.00 FS	*151.20 FS
16	1		*FRONT BUMPER REINFORCEMENT COVER	Cracked	122.00 FS	*97.20 FS
17	1		*HORN - LH	Not Necessary	200.00 FS	*- FS
18	1		*FRONT FENDER - LH	Not Necessary	851.00 FS	*- FS
19	5		*POP RIVET	Not Necessary	17.00 FS	*- FS
20	1		*FRONT FENDER ATTACHMENT PART	Not Necessary	72.00 FS	*- FS
21	1		*FRONT FENDER BRACE - LH	Not Necessary	39.00 FS	*- FS
22	1		*FRONT FENDER BRACKET - LH	Not Necessary	39.00 FS	*- FS
23	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	169.00 FS	*- FS
24	1		*FRONT FENDER ATTACHMENT PART	Not Necessary	89.00 FS	*- FS
25	1		*FRONT BONNET	Dented	3,134.00 FS	*2,507.20 FS
26	1		*FRONT BONNET ATTACHMENT PART	Not Necessary	165.00 FS	*- FS
27	1		*FRONT BONNET CATCH - UPPER	Not Necessary	90.00 FS	*- FS
28	1		*FRONT BONNET STRIKER - LH	Not Necessary	110.00 FS	*- FS
29	1		*FRONT BONNET EDGE PROTECTION	Necessary	28.00 FS	*22.00 FS
30	1		*FRONT BONNET CATCH - LOWER	Not Necessary	63.00 FS	*- FS
31	1		*FRONT BONNET LOCK WITH MICRO SWITCH	Not Necessary	214.00 FS	*- FS
32	1		*FRONT BONNET LOCK COVER	Not Necessary	4.00 FS	*- FS
33	1		*FRONT BONNET BOWDEN CABLE - CENTER	Not Necessary	58.00 FS	*- FS
34	1		*FRONT BONNET BOWDEN CABLE COVER	Not Necessary	10.00 FS	*- FS
35	1		*HEADLIGHT - LH	Cracked	5,455.00 FS	*4,364.00 FS
36	1		*HEADLIGHT LIFT CYLINDER - LH	Not Necessary	142.00 FS	*- FS
37	1		*HEADLIGHT WASHER HOSE	Not Necessary	68.00 FS	*- FS
38	1		*RADIATOR AIR GUIDE - LH	Not Necessary	25.00 FS	*- FS
39	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	12.00 FS	*- FS
40	1		*FRONT NO. PLATE	Necessary	60.00 FS	*60.00 FS
41	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 17,734.00 10,720.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET, AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,000.00
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET	New	3,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (\$\$)	6,702.00
				2,542.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >