

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21009270/APS3Q2**Date:** 03/12/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210079734
Claimant Vehicle No :	SMK1286Z	Insured Vehicle No :	SLU4446T
Date of Loss:	01/09/2021	Nature of Claim:	TP
		Claim No:	7534885702SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK1286Z	Engine No:	B2640441N20B20B
Make & Model:	BMW 520I, 2.0 D/AB 2WD 4DR GAS/D NAV (A)	Chassis No:	WBAXG12080DX53391
Reg. Date:	19/04/2013 (Man. Year: 2013)	Odometer:	126954 km
Colour:	Black		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,921.50	2,116.20	8,805.30	80.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	580.00	1,550.00	72.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,051.50	2,696.20	10,355.30	79.34
Approved Total (Overridden) (S\$)		2,150.00		
(S\$)	13,051.50	2,150.00	10,901.50	83.53
+ GST 7.00/7.00% (S\$)	913.61	150.50	763.11	83.53
Nett Amount (S\$)	13,965.11	2,300.50	11,664.61	83.53
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,602.50		
Global Sum Settlement (S\$)		2,600.00		

INSPECTION

Date of Assignment:	02/09/2021	
Date Inspected:	02/09/2021	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	2.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER AIR DUCT LH	Not Necessary	1,982.60 FL	*- FL
2	1		*REAR BOOT EMBLEM (520I)	Not Necessary	95.00 FL	*- FL
3	1		*REAR BOOT EMBLEM LOGO	Not Necessary	98.00 FL	*- FL
4	1		*REAR BOOT REFLECTOR LAMP R/H	Not Necessary	1,118.40 FL	*- FL
5	1		*REAR END PANEL	Not Necessary	984.10 FL	*- FL
6	1		*REAR TAIL LAMP R/H	Cut	1,336.60 FL	*640.00 FL
7	1		*REAR TAIL LAMP PANEL R/H	Not Necessary	704.60 FL	*- FL
8	1		*REAR BUMPER DIFFUSER	Not Necessary	1,012.30 FL	*- FL
9	1		*REAR BUMPER	Deformed	1,974.00 FL	*1,563.00 FL
10	1		*REAR BUMPER REFLECTOR R/H	Not Necessary	118.20 FL	*- FL
11	1		*REAR BUMPER REINFORCEMENT	Not Necessary	967.70 FL	*- FL
12	1		*REAR BUMPER CENTRE RETAINER	Not Necessary	289.50 FL	*- FL
13	4		*REAR BUMPER REVERSE SENSOR R/H	Not Necessary	1,060.00 FL	*- FL
14	1		*REAR BUMPER SIDE RETAINER R/H	Cracked	265.00 FL	*115.00 FL
15	6		*REAR BUMPER LOWER CLIPS	Necessary	77.40 FS	*30.00 FS
16	3		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	38.70 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,122.10	2,348.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,200.60	231.80
Total Parts (\$\$)	10,921.50	2,116.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET	New	200.00	30.00
2	TUFF KOTE	New	120.00	0.00
3	REMOVE AND REFIX REAR TIMING ETC	New	160.00	0.00
4	REMOVE AND REPLACE REVERSE SENSOR	New	150.00	50.00
5	TO REMOVE AND REPLACE SPARE PART AND PANEL BEATING	New	850.00	250.00
6	TO SPRAY PAINTING AND ETC	New	650.00	250.00
Gross Labour Cost (\$)			2,130.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >