



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JTU 128

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BALANCE LH	CUT	68.00	68.00
1	HANDLE GRIP LH	NOT NECESSARY	195.00	-
1	CLUTCH LEVER LH	CUT	360.00	360.00
1	WING MIRROR LH	CUT	265.00	265.00
1	FRONT SLIDER LH	NOT NECESSARY	290.00	-
1	CENTRE SLIDER LH	CUT	280.00	280.00
1	REAR SLIDER LH	NOT NECESSARY	270.00	-
1	ENGINE COVER (GOLD)	CUT	680.00	680.00
1	ENGINE COVER GARNISH (BLACK)	CRACKED	480.00	480.00
1	FRONT LH FOOTREST	NOT NECESSARY	150.00	-
1	REAR LH FOOTREST	CUT	150.00	150.00
1	REAR CHAIN COVER (CARBON FIBRE)	CUT	480.00	480.00
1	FRONT CLUTCH LEVER	NOT NECESSARY	190.00	-
1	HANDLE BAR LH	NOT NECESSARY	280.00	-
1	SIDE STAND LH	NOT NECESSARY	160.00	-
1	SIDE FAIRING LH	TO REPAIR SEE LABOUR	550.00	-
1	SIDE FAIRING LOWER COVER LH	TO REPAIR SEE LABOUR	480.00	-
	LESS 10% DISCOUNT		-	-276.30
			5,328.00	2,486.70
	<u>LABOUR</u>			
	LABOUR.INCLUSIVE OF THE REPAIR OF SIDE FAIRING LH AND SIDE FAIRING LOWER COVER LH.		300.00	300.00
	SPRAY PAINTING.		300.00	300.00
	WIRING.		50.00	30.00
			650.00	630.00
	GRAND TOTAL		5,978.00	3,116.70



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,500.00
---	--	--	-----------------

Report Ref No. CS/AGI21009272/Avf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.