10/5/21, 11:26 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21009273/R1QF3E2

05/10/2021 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900018655

Claimant Vehicle FBQ1156P Insured Vehicle No: SMP58X No:

Date of Loss: 02/07/2021 Nature of Claim: TP Claim No: 3282239846SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBQ1156P**

HONDA SUPERCUB, 125cc JA48E0002043 Make & Model: Engine No:

Reg. Date: 25/07/2019 (Man. Year: 2019) Chassis No: MLHJA4887K5002043

Odometer: 51016 km Colour: Multi-colour

Engine Capacity: 125 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 80/90-17 Rear Tyre Size: 90/80-17 Front Left Side: Rear Left Side: Maxxis 4 mm Maxxis 4 mm

Front Right Side: $0 \, \text{mm}$ Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 03/09/2021

Race Werks Pte Ltd (HQ) Date Inspected:

Block 1008 Bukit Merah Lane 3, #01-26 03/09/2021 Inspected At:

Singapore 159722

Estimated Period of Repair: 5.0 days

MOHD RASUL Adjuster: Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$10,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRONT RIM	Scratched	0.00 F	*-F
2	1	*FRONT FENDER WHEEL GUARD	Scratched	0.00 F	*- F
3	1	*FRONT FORK ASSY	Repair	0.00 F	*- F
4	1	*FRONT FORK SHAFT	Scratched	0.00 F	*- F
5	1	*FRONT WING MIRROR LH	Scratched	0.00 F	*- F
6	1	*ERP UNIT	Scratched	0.00 F	*- F
7	1	*HANDLE BAR BALANCER LH	Scratched	0.00 F	*- F
8	1	*SIDE FAIRING LH	Scratched	0.00 F	*- F
9	1	*SIGNAL LIGHT SWITCH	Scratched	0.00 F	*- F
10	1	*FRONT FOOT REST	Scratched	0.00 F	*- F
11	1	*FOOT GEAR SHIFTER	Bent	0.00 F	*- F
F=Fra	anchise part.				
			Total Parts (S\$)	0.00	0.00
		Report was unsubmitted d	uring this print-out.		

10/5/21, 11:26 AM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >