

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/GRB21009275/AES3Q2**Date:** 17/01/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SKH1816J	Insured Vehicle No :	SLW4164X
Date of Loss:	02/09/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003863

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH1816J	Engine No:	4A910126249
Make & Model:	MITSUBISHI LANCER, 1.5 (A)	Chassis No:	JMYSRCY2A9U004231
Reg. Date:	01/06/2009 (Man. Year: 2009)	Odometer:	192643 km
Colour:	Black		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,263.44	9,585.70	15,677.74	62.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,430.00	3,480.00	2,950.00	45.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,693.44	13,065.70	18,627.74	58.77
Approved Total (Overridden) (S\$)		10,200.00		
Nett Amount (S\$)	31,693.44	10,200.00	21,493.44	67.82
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		120.00		
Nett Liability (S\$)		11,027.45		
Global Sum Settlement (S\$)		11,000.00		

INSPECTION

Date of Assignment:	03/09/2021	Choo Motor Spray Painter (HQ)
Date Inspected:	03/09/2021 Inspected At:	1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit
Estimated Period of Repair:	12.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE

MARKET VALUE: \$22,000
LTA REBATE: \$6,573
NETT VALUE: \$15,427

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Nov 2021)
Parts:	143	MITSUBISHI LANCER 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKH1816J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID BOARD	Distorted	347.00 FL	*230.00 FL
2	1		*REAR THIRD BRAKE LIGHT	Cracked	452.00 FL	*125.00 FL
3	2		*REAR BOOT LID REFLECTOR	Cracked	790.00 FL	*580.00 FL
4	1		*REAR BOOT LID	Distorted	1,025.00 FL	*850.00 FL
5	1		*REAR BOOT RUBBER	Cut	325.00 FL	*185.00 FL
6	1		*REAR BOOT LOCK	Jammed	282.00 FL	*282.00 FL
7	1		*REAR BOOT LOCK CATCH	Bent	75.00 FL	*75.00 FL
8	2		*REAR BOOT HINGE	Bent	370.00 FL	*250.00 FL
9	1		*REAR BOOT EMBLEM (MIVEC)	Necessary	85.00 FL	*85.00 FL
10	1		*REAR BOOT EMBLEM (LANCER)	Necessary	85.00 FL	*85.00 FL
11	2		*REAR BOOT LID HINGES ABSORBER HOLDER	Damaged	450.00 FL	*450.00 FL
12	1		*REAR BOOT CENTRE LOGO	Necessary	82.00 FL	*82.00 FL
13	1		*REAR END PANEL	Distorted	655.00 FL	*550.00 FL
14	1		*REAR END PANEL TOP GARNISH	Distorted	285.00 FL	*285.00 FL
15	2		*REAR CHASSIS NUMBER	Repair	1,510.00 FL	*- FL
16	2		*REAR SPARE TYRE BOARD CORNER PANEL	Buckled	550.00 FL	*550.00 FL
17	1		*REAR BUMPER CENTRE BEAM	Distorted	125.00 FL	*125.00 FL
18	1		*REAR SPARE TYRE BOARD TOP COVER CLOTH	Not Necessary	145.00 FL	*- FL
19	2		*REAR TAIL LAMP	Cracked	1,498.00 FL	*700.00 FL
20	2		*REAR TAIL LAMP PANEL	Distorted	330.00 FL	*330.00 FL
21	1		*REAR FENDER	O/S Buckled	1,790.00 FL	*895.00 FL
22	2		*REAR FENDER INNER GARNISH	Torn	830.00 FL	*290.00 FL
23	2		*REAR FENDER DUST COVER	Not Necessary	80.00 FL	*- FL
24	1		*REAR BUMPER	Distorted	948.00 FL	*830.00 FL
25	2		*REAR BUMPER SIDE RETAINER	Necessary	120.00 FL	*120.00 FL
26	1		*REAR BUMPER REINFORCEMENT	Bent	655.00 FL	*325.00 FL
27	2		*REAR BUMPER REFLECTOR	Cracked	94.00 FL	*94.00 FL
28	1		*REAR SPARE TYRE PANEL	Distorted	1,012.00 FL	*1,012.00 FL
29	1		*REAR SPARE TYRE TOP COVER BOARD	Torn	350.00 FL	*350.00 FL
30	1		*REAR SPARE TYRE SCREW	Damaged	68.00 FL	*68.00 FL
31	1		*REAR EXHAUST SILENCER	Not Necessary	1,450.00 FL	*- FL
32	2		*REAR LOWER ARM	Not Necessary	710.00 FL	*- FL
33	1		*REAR BLIND SPOT SENSOR	Not Necessary	552.00 FL	*- FL
34	1		*REAR EXHAUST CHROME PIPE	Not Necessary	125.00 FL	*- FL
35	1		*REAR BOOT LOCK ANTENNAE	Not Necessary	255.00 FL	*- FL
36	2		*REAR SHOCK ABSORBER	Not Necessary	830.00 FL	*- FL
37	2		*REAR KNUCKLE ARM	Not Necessary	1,304.60 FL	*- FL
38	2		*REAR EXHAUST RUBBER	Not Necessary	82.00 FL	*- FL
39	2		*REAR WHEEL BEARING HUB	Not Necessary	790.00 FL	*- FL
40	2		*REAR NUMBER PLATE LAMP	Cracked	120.00 FL	*120.00 FL
41	1		*REAR WINDSCREEN MLDG	Necessary	145.00 FL	*145.00 FL
42	3		*REAR END PANEL TOP GARNISH CLIPS	Necessary	19.50 FS	*19.50 FS
43	1		*REAR SPARE TYRE PANEL TOP INSULATOR	Necessary	250.00 FS	*200.00 FS
44	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
45	1		*REAR NUMBER PLATE	Bent	45.00 FS	*45.00 FS
46	1		*REAR BUMPER SENSOR	Damaged	450.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

1/17/22, 11:18 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR REVERSING CAMERA	Not Necessary	650.00 FS	*- FS
48	1		*SET TAIL LAMP MASK	Not Necessary	150.00 FS	*- FS
49	1		*REAR BOOT COVER TOP SPOILER	Not Necessary	2,200.00 FS	*- FS
50	1		*REAR BOOT COVER TOP SPOILER (SMALL)	Not Necessary	1,800.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					27,441.10	10,592.50
- List Item Discount on L Items 10.00/10.00% (S\$)					2,177.66	1,006.80
Total Parts (S\$)					25,263.44	9,585.70
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	250.00	30.00
2	TUFF KOTE	New	200.00	100.00
3	REMOVE AND REFIX REAR WINDSCREEN	New	150.00	120.00
4	REMOVE AND REFIX UPHOLSTERY	New	250.00	180.00
5	REMOVE AND REPLACE EXHAUST PIPE	New	160.00	0.00
6	REMOVE AND REPLACE REVERSE SENSOR	New	150.00	50.00
7	TO REMOVE AND REPLACE SPARE PART AND PANEL BEATING	New	2,800.00	1,600.00
8	TO SPRAY PAINTING AND ETC	New	1,800.00	1,400.00
9	REMOVE AND REFIX REAR UNDERCARRIAGE SUSPENSION ETC	New	550.00	0.00
10	CHECK WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (\$\$)			6,430.00	3,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >