

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009277/R1UCN2**Date:** 02/11/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00097652100

Claimant Vehicle No : SMK181Z **Insured Vehicle No :** SMR5669P

Date of Loss: 01/09/2021 Nature of Claim: TP Claim No: SNM21D204917/C2/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMK181Z**

Make & Model: VOLVO XC90, 2.0 T5 (A) Engine No: B4204T232075447

Reg. Date: 28/07/2017 (Man. Year: 2017) Chassis No: YV1LF10ACH1187723

Colour: Grey Odometer: 84685 km

Engine Capacity: 1969 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 275/35R22 Rear Tyre Size: 275/35R22

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,730.80	6,747.30	2,983.50	30.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,970.00	2,545.00	1,425.00	35.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,700.80	9,292.30	4,408.50	32.18
+ GST 7.00/7.00% (S\$)	959.06	650.46	308.60	32.18
Nett Amount (S\$)	14,659.86	9,942.76	4,717.10	32.18

INSPECTION

Date of Assignment: 03/09/2021

Date Inspected: 18/10/2021 Inspected At: Wearnes Automotive Pte Ltd (Alexandra Road)
249 Alexandra Road
Singapore 159935

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 29 Oct 2021)
Parts: M1-SUV	VOLVO XC90 2.0 T5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK181Z)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER SPOILER CTR X	Scratched	323.10 FS	*290.79 FS
2	1		*BUMPER SPOILER FRT L	Scratched	323.10 FS	*290.79 FS
3	1		*BUMPER SPOILER FRT R	Serviceable	323.10 FS	*- FS
4	1		*V039841726/BUMPER CO	Scratched	2,670.30 FS	*2,403.27 FS
5	1		*BUMPER BRACKET FRT L	Serviceable	91.60 FS	*- FS
6	1		*BUMPER BRACKET FRT R	Serviceable	91.60 FS	*- FS
7	1		*BUMPER BRACKET FRT L	Serviceable	91.60 FS	*- FS
8	1		*BUMPER BRACKET FRT R	Serviceable	91.60 FS	*- FS
9	1		*RADIATOR GRILLE T5 X	Cracked	1,260.10 FS	*1,134.09 FS
10	1		*BUMPER GRILLE LH CHR	Bent	366.70 FS	*330.03 FS
11	1		*BUMPER GRILLE RH CHR	Necessary	366.70 FS	*330.03 FS
12	1		*NUMBER PLATE RETAINE	Cut	63.30 FS	*56.97 FS
13	10		*WIPER GRILLE CLIP XC	Necessary	83.00 FS	*74.70 FS
14	1		*BUMPER GRILLE LOWER	Scratched	231.70 FS	*208.53 FS
15	1		*PROTECTING PLATE FRT	Scratched	742.90 FS	*668.61 FS
16	1		*BUMPER RAIL FRT XC90	Serviceable	1,544.30 FS	*- FS
17	10		*BLIND RIVET 4.0*21 P	Necessary	41.00 FS	*36.90 FS
18	10		*BUMPER CLIP 8X8,5	Necessary	68.00 FS	*61.20 FS
19	1		*BUMPER INSTALLING MT	Necessary	96.50 FS	*86.85 FS
20	1		**D* ADHESIVE CHEMICA	Necessary	797.60 FS	*717.84 FS
21	10		*EXPANDING NUT XC40 1	Necessary	63.00 FS	*56.70 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	9,730.80	6,747.30
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER,FRT GRILLE,FRT LOWER SPOILER,ETC	New	1,700.00	850.00
2	TO PUTTY SPRAY PAINT ON FRT BUMPER,ETC	New	1,700.00	1,125.00
3	TO INSTALL FRONT NUMBER PLATE INCLUDE HOLDER	New	60.00	60.00
4	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	510.00	510.00
			Gross Labour Cost (\$)	3,970.00
				2,545.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >