

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21009278/GVCQ2**Date:** 16/12/2022**REFERENCE**

Insured/Claimant: KAMARON XAMAN BIN YAHYA Policy No: DMB1SNW00000732101

Date of Loss: 20/08/2021

Nature of Claim: OD

Claim No: SNM21D204764/C1/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **CB7198X**
 Make & Model: TOYOTA COASTER, 4.0 D (M) Engine No: N04CUH17001
 Reg. Date: 17/07/2013 (Man. Year: 2013) Chassis No: JTGFP538003500536
 Colour: White Odometer: 0 km
 Engine Capacity: 4009 cc
 Market Value/New Car Price: S\$32,000.00
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/75 R17.5 Rear Tyre Size: 215/75 R17.5
 Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm
 Front Right Side: Firenza 6 mm Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	10,391.00	-10,391.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	2,700.00	-2,700.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	0.00	13,091.00	-13,091.00	
- Excess (\$\$)	0.00	2,000.00	-2,000.00	
(\$\$)	0.00	11,091.00	-11,091.00	
+ GST 7.00/7.00% (\$\$)	0.00	776.37	-776.37	
Nett Amount (\$\$)	0.00	11,867.37	-11,867.37	

INSPECTION

Date of Assignment: 03/09/2021 Present Location: SC Auto Industries (S) Pte Ltd (HQ)
 Date Inspected: 02/09/2021 Inspected At: SC Auto Industries (S) Pte Ltd (HQ)
 51 Senoko Road, #03-01
 Singapore 758133
 Estimated Period of Repair: 10.0 days

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Dec 2022)	
Parts:	N/A	TOYOTA COASTER 4.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for CB7198X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	4		*PISTON SET ,W/PISTON RING (WCP)	Damaged	-	*1,312.00 F
2	4		*LINER CYL S/S (WCP)	Damaged	-	*1,392.00 F
3	1		*PISTON PIN (WCP)	Damaged	-	*68.00 F
4	1		*CONROD (WCP)	Damaged	-	*385.00 F
5	1		*CLIP (WCP)	Not Necessary	-	*- F
6	1		*BEARING ,CONNECTING ROD (WCP)	Damaged	-	*165.50 F
7	1		*SET BEARING (WCP)	Damaged	-	*240.00 F
8	1		*GASKET KIT ENGINE (WCP)	Necessary	-	*760.00 F
9	1		*GUM (GASKET MARKET) (ULTRA GREY) (WCP)	Necessary	-	*18.00 F
10	1		*PUMP ASSY ,WATER (WCP)	Not Working	-	*290.00 F
11	1		*THERMOSTAT O RING (WCP)	Damaged	-	*15.00 F
12	1		*THERMOSTAT (WCP)	Not Working	-	*85.00 F
13	1		*PULLEYSUB-ASSY ,IDLER (WCP)	Not Necessary	-	*- F
14	1		*PULLEY ,COOLER COMPRESSOR IDLER (WCP)	Not Necessary	-	*- F
15	2		*AIR CON BELT (WCP)	Damaged	-	*32.00 F
16	2		*ALTERNATOR BELT (WCP)	Damaged	-	*46.00 F
17	1		*COVER ASSY ,CLUTCH (WCP)	Not Necessary	-	*- F
18	1		*DISC ASSY ,CLUTCH (WCP)	Damaged	-	*340.00 F
19	1		*BEARING ,CLUTCH (WCP)	Damaged	-	*130.00 F
20	1		*FLYWHEEL BEARING (WCP)	Damaged	-	*20.00 F
21	2		*FRONT ENGINE MOUNTING (WCP)	Not Necessary	-	*- F
22	1		*HOSE ,WATER BY-PASS (S) (WCP)	Not Necessary	-	*- F
23	1		*HOSE ,WATER BY-PASS (B) (WCP)	Not Necessary	-	*- F
24	1		*ENGINE OIL (WCP) (7.5 PCS)	Necessary	-	*90.00 F
25	1		*OIL FILTER (WCP)	Damaged	-	*40.00 F
26	1		*FUEL FILTER (WCP)	Damaged	-	*25.00 F
27	2		*COOLANT (WCP)	Necessary	-	*56.00 F
28	1		*REAR BRAKE SHOE (WCP)	Not Necessary	-	*- F
29	8		*BRAKE CUP (WCP)	Not Necessary	-	*- F
30	2		*RR WHEEL HUB SEAL INNER (WCP)	Necessary	-	*70.00 F
31	3		*GEARMAX 85W140 (GL-5) (WCP)	Necessary	-	*36.00 F
32	4		*GEARMAX 85W90 (GL-5) (WCP)	Necessary	-	*48.00 F
33	1		*RELAY ASSY ,DOOR (WCP)	Not Working	-	*2,485.50 F
34	2		*RR HUB SEAL OUTER (WCP)	Necessary	-	*30.00 F
35	1		*BRAKE FLUID (WCP)	Necessary	-	*12.00 F
36	1		*PLYWOOD (7 PCS)	Damaged	-	*1,000.00 FS
37	1		*ECU	Not Working	-	*1,200.00 FS
38	1		*SUNDRIES (WCP)	Not Necessary	-	*- F

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **0.00** **10,391.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR GENERAL OVERHAUL AND CHECK WIRE HARNESS CHECK AND SERVICE ACCORDING TO DAMAGE	New	-	1,450.00
2	LABOUR TO REMOVE ,REFIT AND REINSTALL PLYWOOD	New	-	500.00
3	LABOUR FOR CLEANING	New	-	450.00
4	LABOUR TO REMOVE ,REFIT AND REINSTALL UPHOLSTERY ALL SEAT COMPARTMENT	New	-	300.00
5	LABOUR TO CARRY OUT DIAGNOSTIC CHECK	New	-	0.00
Gross Labour Cost (\$\$)			0.00	2,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >