



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 7772J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT WINDSCREEN	CRACKED	1,582.40	1,288.00
1	FRT WINDSCREEN MOULDING	NECESSARY	372.90	250.00
1	WIPER BLADE RH	DENTED / BENT	81.20	40.00
1	WIPER ARM RH	DENTED / BENT	114.50	114.50
1	WIPER BLADE LH	NOT NECESSARY	86.30	-
1	WIPER ARM LH	NOT NECESSARY	110.40	-
1	WIPER ARM CAP LH	DENTED / CRACKED	9.70	9.70
2	WIPER NOZZLE R/L @\$58.60	BROKEN	117.20	117.20
1	WIPER ARM CAP LINK ROD ASSY	NOT NECESSARY	298.70	-
1	WIPER MOTOR	NOT NECESSARY	760.70	-
1	FRT WIPER GARNISH	DENTED / DISTORTED	301.60	301.60
1	FRT PANEL TOP INNER MEMBER	TO REPAIR SEE LABOUR	482.30	-
1	FRT PANEL TOP GARNISH (BLACK)	DENTED / LOOP BROKEN	325.50	325.50
1	FRT PANEL OUTER	TO REPAIR SEE LABOUR	834.60	-
1	FRT EMBLEM (DYNA)	NECESSARY	63.90	63.90
1	FRT GRILLE ASSY	NOT NECESSARY	600.50	-
1	FRT PANEL OUTER (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-1,535.60	-627.60
			4,606.80	1,882.80
<u>SPECIAL NETT ITEMS</u>				
1	ERP BRACKET (SN)	NECESSARY	26.00	26.00
			26.00	26.00
<u>LABOUR</u>				
	TO REMOVE AND REINSTALL ELECTRICAL WIRING SYSTEM FOR NECESSARY REPAIRS. TO CHECK ELECTRICAL SYSTEM, REPAIR WIRE HARNESS AND FOCUS HEADLAMP.		70.00	30.00

Report Ref No. CS3/LPC21006224/Etf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REPLACE AND REINSTALL FRONT WINDSCREEN.		120.00	120.00
	TO REMOVE, REPLACE AND REINSTALL DASHBOARD ASSY.		350.00	200.00
	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRT PANEL TOP INNER MEMBER AND FRT PANEL OUTER.		800.00	400.00
	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA.		800.00	400.00
			2,140.00	1,150.00
GRAND TOTAL			6,772.80	3,058.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,450.00

Report Ref No. CS3/LPC21006224/Etf3e2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.