

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009281/BTCN2**Date:** 06/10/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00081132000	
Claimant Vehicle No :	SNA9624U	Insured Vehicle No :	XD8106X	
Date of Loss:	28/08/2021	Nature of Claim:	TP	Claim No: SNM21D204860/C02/PAULINE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA9624U		Engine No:	36569750B37D15A
Make & Model:	BMW 116D, 1.5 (A)		Chassis No:	WBA1V72010V725456
Reg. Date:	16/11/2016 (Man. Year: 2016)		Odometer:	66522 km
Colour:	Grey			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40R18	Rear Tyre Size:	225/40R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,657.95	6,442.07	10,215.88	61.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	1,500.00	1,900.00	55.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,057.95	7,942.07	12,115.88	60.40
Approved Total (Overridden) (\$\$)		6,350.00		
(\$\$)	20,057.95	6,350.00	13,707.95	68.34
+ GST 7.00/7.00% (\$\$)	1,404.06	444.50	959.56	68.34
Nett Amount (\$\$)	21,462.01	6,794.50	14,667.51	68.34

INSPECTION

Date of Assignment:	03/09/2021	
Date Inspected:	06/09/2021 Inspected At:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Oct 2021)
Parts:	144	BMW 116D 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA9624U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR R/H	Dented	1,650.95 F	*1,380.20 FL
2	2		*REAR DOOR HINGE R/H	Bent	455.60 F	*230.00 FL
3	1		*REAR DOOR BOARD R/H	Broken	437.50 F	*437.50 FL
4	1		*REAR GLASS R/H	Broken	258.30 F	*258.30 FL
5	1		*REAR DOOR OUTER MOULDING R/H	Bent	153.30 F	*153.30 FL
6	1		*REAR PILLAR R/H	Not Damaged	883.50 F	*- FL
7	1		*REAR BUMPER	Cut	1,424.45 F	*1,220.30 FL
8	1		*REAR BUMPER REINFORCEMENT	Not Damaged	878.55 F	*- FL
9	1		*REAR BUMPER SIDE BRACKET R/H	Necessary	151.85 F	*151.85 FL
10	2		*REAR CLOM H	Not Damaged	227.00 F	*- FL
11	1		*REAR DOOR HANDLE	Dented	166.10 F	*166.10 FL
12	1		*REAR FENDER R/H	Dented	786.20 F	*786.20 FL
13	1		*REAR FENDER SUPPORT BRACKET R/H	Not Necessary	161.35 F	*- FL
14	1		*REAR FENDER COWLING R/H	Not Necessary	216.60 F	*- FL
15	1		*ROCKER PANEL RH	Cut	407.25 F	*407.25 FL
16	1		*REAR KNUCKLE ARM RH	Dented	594.10 F	*594.10 FL
17	1		*REAR SHOCK ABSORBER RH	Bent	610.90 F	*386.70 FL
18	1		*REAR STEERING RACK AND PINION	No such part	3,286.25 F	*- FL
19	1		*REAR REGULATOR	Bent	329.40 F	*253.95 FL
20	1		*REAR REGULATOR MOTOR	Short Circuit	583.80 F	*323.80 FL
21	1		*TAIL LAMP R/H	Not Damaged	840.35 F	*- FL
22	1		*TAIL LAMP BRACKET R/H	Not Damaged	112.65 F	*- FL
23	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
24	8		*REAR FENDER COWLING CLIPS	Not Necessary	40.00 FS	*- FS
25	1		*WHEEL RIM FRONT R/H	Not Necessary	1,526.00 FS	*- FS
26	1		*FRONT WHEEL R/H	Not Damaged	426.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,657.95	6,779.55
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	337.48
Total Parts (\$\$)	16,657.95	6,442.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR ACCIDENT AFFECTED AREA	New	1,600.00	800.00
2	SPRAY PAINTING	New	1,500.00	600.00
3	CHECK ALIGNMENT	New	200.00	60.00
4	REALIGN REAR WHEEL	New	100.00	40.00
Gross Labour Cost (\$\$)			3,400.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >