

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21009284/KVCN2**Date:** 09/11/2021**REFERENCE**

Insured/Claimant: PHUA RAYMOND Policy No: DMPCSNW00148232101

Date of Loss: 31/08/2021 Nature of Claim: OD Claim No: SNM21D204888/C01/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SDB8899M**

Make & Model: BENTLEY CONTINENTAL GTC, 6.0 (A)

Engine No: CKH014110

Reg. Date: 07/02/2013 (Man. Year: 2012)

Chassis No: SCBGE23W9DC081180

Colour: Metallic Pearl Grey

Odometer: 49410 km

Engine Capacity: 5998 cc

Market Value/New Car Price: S\$316,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/35 ZR21

Rear Tyre Size: 275/35 ZR21

Front Left Side: Pirelli 9 mm

Rear Left Side: Pirelli 9 mm

Front Right Side: Pirelli 9 mm

Rear Right Side: Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	78,911.64	72,197.80	6,713.84	8.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	2,310.00	1,340.00	36.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	82,561.64	74,507.80	8,053.84	9.75
- Excess (S\$)	10,000.00	10,000.00	0.00	0.00
(S\$)	72,561.64	64,507.80	8,053.84	11.10
+ GST 7.00/7.00% (S\$)	5,079.31	4,515.55	563.76	11.10
Nett Amount (S\$)	77,640.95	69,023.35	8,617.60	11.10

INSPECTION

Date of Assignment: 03/09/2021

Date Inspected: 03/09/2021 Inspected At:

Estimated Period of Repair: 6.0 days

BLK 5033

ANG MO KIO INDUSTRIAL PARK 2

#01-259

SINGAPORE 569536

REPAIRER: ESTEEM PERFORMANCE PTE LTD

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Nov 2021)	
Parts:	N/A	BENTLEY CONTINENTAL GTC 6.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDB8899M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP LH	Mtg Cracked	9,900.00 FL	*9,900.00 FL
2	1		*HEADLAMP RH	Mtg Cracked	9,900.00 FL	*9,900.00 FL
3	1		*HEADLAMP CHROME LH	Distorted	324.00 FL	*324.00 FL
4	1		*HEADLAMP CHROME RH	Mtg Cracked	324.00 FL	*324.00 FL
5	1		*SIGNAL LAMP CHROME LH	Serviceable	306.00 FL	*- FL
6	1		*SIGNAL LAMP CHROME RH	Serviceable	306.00 FL	*- FL
7	1		*FRONT SUPPORT PANEL	Repair	2,340.00 FL	*- FL
8	1		*FRONT SUPPORT PANEL LOWER	Repair	666.00 FL	*- FL
9	1		*CONDENSER	Punctured	1,800.00 FL	*1,800.00 FL
10	1		*RADIATOR }	Punctured	2,628.00 FL	*2,628.00 FL
11	1		*RADIATOR FAN BLADE }		0.00 FL	*- FL
12	1		*RADIATOR AIR GUIDE RH	Cracked	108.00 FL	*108.00 FL
13	1		*RADIATOR AIR GUIDE LH	Cracked	108.00 FL	*108.00 FL
14	1		*FRONT BUMPER	Mtg Cracked	8,244.00 FL	*8,244.00 FL
15	10		*FRONT BUMPER CLIP	Necessary	200.00 FL	*200.00 FL
16	1		*FRONT BUMPER REINFORCEMENT	Repair	2,250.00 FL	*- FL
17	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	117.00 FL	*- FL
18	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	117.00 FL	*- FL
19	1		*FRONT BUMPER SPONGE (NPA)	No such part	0.00 FL	*- FL
20	1		*FRONT GRILLE	Cracked	3,960.00 FL	*3,960.00 FL
21	1		*FRONT GRILLE MESH	Cracked	1,242.00 FL	*1,242.00 FL
22	1		*FRONT GRILLE CHROME	Cracked	1,728.00 FL	*1,728.00 FL
23	1		*FRONT GRILLE RUBBER	Serviceable	234.00 FL	*- FL
24	1		*FRONT GRILLE EMBLEM (NPA)	Not Necessary	0.00 FL	*- FL
25	1		*FRONT BUMPER LOWER GRILLE MESH LH	Mtg Cracked	1,224.00 FL	*1,224.00 FL
26	1		*FRONT BUMPER LOWER GRILLE MESH RH	Mtg Cracked	1,224.00 FL	*1,224.00 FL
27	1		*FOG LAMP MESH LH	Cracked	756.00 FL	*756.00 FL
28	1		*FOG LAMP MESH RH	Cracked	756.00 FL	*756.00 FL
29	6		*FRONT BUMPER SENSOR	Serviceable	1,080.00 FL	*- FL
30	6		*FRONT BUMPER SENSOR COVER	Serviceable	21.60 FL	*- FL
31	1		*LH FRONT FENDER	Bent	14,040.00 FL	*14,040.00 FL
32	1		*RH FRONT FENDER	Bent	14,040.00 FL	*14,040.00 FL
33	1		*FRONT SUPPORT TOP PANEL	Buckled	864.00 FL	*864.00 FL
34	1		*FRONT GRILLE TOP PANEL	Cracked	324.00 FL	*324.00 FL
35	1		*FRONT GRILLE TOP PANEL COVER	Cracked	360.00 FL	*360.00 FL
36	1		*FRONT GRILLE MESH SIDE BRACKET LH	Distorted	153.00 FL	*153.00 FL
37	1		*FRONT GRILLE MESH SIDE BRACKET RH	Distorted	153.00 FL	*153.00 FL
38	1		*FRONT BUMPER REINFORCEMENT LOWER COVER	Cracked	270.00 FL	*270.00 FL
39	1		*ENGINE OIL COOLER	Punctured	4,320.00 FL	*4,320.00 FL
40	1		*FRONT GRILLE MESH RH	Cracked	1,242.00 FL	*1,242.00 FL
41	1		*FRONT NUMBER PLATE	Cracked	45.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	87,674.60	80,217.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	8,762.96	8,019.20
Total Parts (\$\$)	78,911.64	72,197.80

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(BONNET,FRONT BUMPER,SUPPORT PANEL,LHF FENDER,RHF FENDER)	New	1,400.00	800.00
2	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(BONNET,FRONT BUMPER,SUPPORT PANEL,LHF FENDER,RHF FENDER)	New	1,600.00	1,200.00
3	TO CHECK WIRING,FOCUS HEADLAMP	New	50.00	30.00
4	TO REMOVE & REFIT RADIATOR TO ASSIST WORK LOAD	New	200.00	100.00
5	TO REMOVE & REFIT AIRCON CONDENSOR TO ASSIST WORK LOAD,TO TOP UP A/C GAS	New	200.00	100.00
6	TO REMOVE & REFIT FRONT SENSOR	New	200.00	80.00
Gross Labour Cost (\$\$)			3,650.00	2,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >