Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Chee So Chow Date: 03 Sep 2021

Preliminary Advice

Vehicle No : SDB8899M **Accident Date** : 31/08/2021

: BENTLEY CONTINENTAL GTC Policy No. Make

DMPCSNW00148232101

Assignment Date : 03/09/2021 Excess : S\$10.000.00

Est. Duration of Repair Date of Inspection : 03/09/2021

: ESTEEM PERFORMANCE PTE LTD (HQ) Inspection At

176 SIN MING AUTOCARE SIN MING DRIVE, #01-14 & #01-15 & #01-16

SINGAPORE 575721

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 75,644.24 |
|-----------------------------|------|-----------|
| Revised Amount | :S\$ | 33,935.60 |
| Check Items (Estimated) | :S\$ | 36,223.24 |
| Total | :S\$ | 70,158.84 |

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 316,000.00 COE / PARF Rebate :S\$ 136,952.00

Salvage Value :S\$

Margin for Repair :S\$ 179,048.00

Remarks

| (X) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. It | Cindly |
|-------|---------------------------------------------------------------------------------------------------------|--------|
| | let us have your authorisation. | |

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject (X) to part prices and labour cost check.