



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 6863C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	R/L FENDER	TO REPAIR SEE LABOUR	1,500.00	-
1	REAR BUMPER	CUT	955.00	745.00
1	R/L SIDE BUMPER	TORN	300.00	195.00
1	R/L FENDER WHEEL ARCH MOULDING	CUT	300.00	175.20
	LESS 20% DISCOUNT		-611.00	-223.04
			2,444.00	892.16
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
			80.00	30.00
	<u>LABOUR</u>			
	TO LABOUR CHARGE FOR REMOVING R/L FENDER, REAR BUMPER, OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS. ALSO INCLUDE CUTTING OUT AND WELDING OF REPLACEMENT SPARE TYRE PANEL. INCLUSIVE OF THE REPAIR OF R/L FENDER.		1,000.00	500.00
	TO RESPRAY REAR TAILGATE, END PANEL AND SPARE TYRE PANEL.		800.00	500.00
			1,800.00	1,000.00
GRAND TOTAL			4,324.00	1,922.16
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CS/SMR21009288/Gny3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.