

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Yr Regn:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:)

) - RS + RS SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL

10/1/13 4s \$5800 informed E/in

Sp. Alan Asher



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Car Number: SMJ6523L

Model : BMW 316I

Damaged Area: (Rear Damaged)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

*not Authorized
mercy
6/9/21 1/5 \$5800
5 days.*

Parts / Material :

1	Rear Bumper			\$ 1,486.70	✓
2	Rear Bumper Side Retainer	o/s	Dis CRA	\$ 98.80	✓
3	Rear Bumper Beam		Dis	\$ 337.40	✓
4	Rear Bumper Centre	Kick up sensor	CRA	\$ 197.80	✓
5	Rear Bumper Lower		Dis / torn	\$ 486.20	✓
6	Rear Bumper Sensor @ SGD 275.60		shook 21842-430	\$ 1,102.40	2pc
7	Rear Bumper Sensor Bracket Set		AN	\$ 97.30	X
8	Rear Bumper Reflector @ SGD 175.80		o/s CRA 68	\$ 351.60	1pc
9	Rear Bumper Tow Garnish		Torn 45	\$ 68.70	✓
10	Rear Bumper Clips		new	\$ 60.00	✓
11	Rear End Panel Top Garnish		TW 315.00	\$ 495.80	✓
12	Rear End Panel		TD / bent	\$ 986.20	✓
13	Rear End Panel top Garnish Clips		11	\$ 66.00	X
14	Rear Bootlid Panel		11	\$ 1,571.30	X
15	Rear Bootlid Inner Trim Garnish		11	\$ 486.20	X
16	Rear Bootlid Inner Trim Garnish Clips		11	\$ 60.00	X
17	Rear Bootlid Inner Lock		11	\$ 425.10	X
18	Rear Bootlid Centre Logo		new 90	\$ 112.40	✓
19	Rear Bootlid Weather Strip		11	\$ 368.50	X
20	Rear Bootlid Reflector Lamp @ SGD 528.70		11	\$ 1,057.40	X
21	Rear Taillamps @ 925.40		OTS / CR 825	\$ 1,850.80	1pc
22	Rear Fender Inner Trim Garnish @ 586.20		11	\$ 1,172.40	X
23	Rear Fender Inner Trimboard Clips		11	\$ 60.00	X
24	Rear Spare Tyre Top Carpet Trim		11	\$ 425.80	X
25	Rear Exhaust Chrome Muffler		11	\$ 120.00	X
26	Rear Exhaust End Pipe		11	\$ 1,186.20	X
27	Rear Exhaust heat shield		new	\$ 108.40	✓

Parts : \$ 14,839.40

Less Parts 5% : \$ 741.97

Total Parts : \$ 14,097.43

Special Net Items :

Rear End Panel Sealant	11	\$ 80.00	50
Rear Floor Panel Insulator	11	\$ 230.00	X
Rear Bumper Lower Spoiler (Accessories)	Repeat	\$ 720.00	X
Rear Exhaust Gum	11	\$ 110.00	X
Rear Number Plate W/Garnish	11	\$ 65.00	X

Total S/N Parts : \$ 1,225.00

Labour :

To Remove, Repair & Renew Rear Affected Accident Areas
 To Putty, Spray Paint on Affected Accident Areas
 To Check & Re-Connect all electrical wiring
 To Remove & Install Rear Tailgate Components Trim & Garnish
 To Remove & Install Rear Spare Tyre Components, Trim & Garnish
 To Re-Position, Drill & Install Reverse Sensor
 To Conduct Water Leakage Test
 To Rust Proof Affected Areas

\$ 1,200.00 850
 \$ 1,200.00 900
 \$ 50.00 30
 ^ ^ \$ 150.00 X
 \$ 150.00 80
 \$ 150.00 50
 ^ ^ \$ 150.00 X
 \$ 200.00 40

Total Labour : \$ 3,250.00

TOTAL PARTS : \$ 14,097.43
TOTAL SPECIAL NET ITEM : \$ 1,225.00
TOTAL LABOUR : \$ 3,250.00
TOTAL REPAIR COST : \$ 18,572.43

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

FINALISED AMOUNT :

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9-5534.5
 57
 9-5257.77
 S.N - 50
 2-1950
 7257.77