

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG21009297/VRS3Q2

Date:

11/11/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SHB8344A

Date of Loss: 01/09/2021

Policy No:

Insured Vehicle No :

Nature of Claim:

SKW8355Y

TP

Claim No:

6662259513SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHB8344A**

Make & Model: HYUNDAI I30, 1.6 (A)

Reg. Date: 16/08/2017 (Man. Year: 2016)

Colour: Silver

Engine Capacity: 1582 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No:

D4FBGZ127655

Chassis No:

TMAD281UVHJ131318

Odometer:

340881 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Handbrake (Serviceable):

Yes

Steering (Serviceable):

Engine Modification:

Yes

No

Footbrake (Serviceable):

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Front Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Tyre Size:

195/65 R15

Rear Left Side:

West Lake 5 mm

Rear Right Side:

West Lake 5 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,653.23	1,487.26	3,165.97	68.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,090.00	970.00	1,120.00	53.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,743.23	2,457.26	4,285.97	63.56
Approved Total (Overridden) (S\$)		1,900.00		

(S\$)	6,743.23	1,900.00	4,843.23	71.82
+ GST 7.00/7.00% (S\$)	472.03	133.00	339.03	71.82
Nett Amount (S\$)	7,215.26	2,033.00	5,182.26	71.82
+ Loss of Use (3.5 x S\$50.00/day) (S\$)		175.00		
+ Car Rental (3.5 x S\$62.06/day) (S\$)		217.21		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,427.21		

INSPECTION

Date of Assignment: 03/09/2021

Date Inspected: 06/09/2021

Inspected At:

Premier Automotive Services Pte Ltd (HQ)
 23 Changi South Ave 2, #01-02
 Singapore 486443

Estimated Period of Repair: 3.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LOWER GARNISH	Cut	362.61 FL	*362.61 FL
2	1		*TAILGATE	Repair	2,292.30 FL	*- FL
3	2		*TAILGATE HINGE	Serviceable	57.00 FL	*- FL
4	1		*TAILGATE WEATHERSTRIP	Serviceable	276.98 FL	*- FL
5	1		*TAILGATE STRIKER	Serviceable	36.50 FL	*- FL
6	1		*TAILGATE EMBLEM I30	Necessary	27.80 FL	*27.80 FL
7	1		*EMBLEM CRDI	Necessary	29.40 FL	*29.40 FL
8	1		*EMBLEM HYUNDAI LOGO	Necessary	29.40 FL	*29.40 FL
9	1		*REAR BUMPER	Deformed	811.11 FL	*811.11 FL
10	1		*REAR BUMPER SPONGE	Serviceable	79.20 FL	*- FL
11	1		*REAR BUMPER REINFORCEMENT	Serviceable	815.64 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT CENTRE	Serviceable	79.20 FL	*- FL
13	1		*REAR BUMPER N/S & O/S SIDE BRACKET	Serviceable	104.40 FL	*- FL
14	1		*REAR BUMPER N/S & O/S REFLECTOR	O/S Serviceable / N/S Cracked	107.50 FL	*53.75 FL
15	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
16	1		*SET REVERSE SENSOR	Cut	280.00 FS	*200.00 FS
17	1		*SET TAILGATE STICKERS	Necessary	100.00 FS	*100.00 FS
18	1		*SET TAILGATE LOWER GARNISH CLIPS	Necessary	38.00 FS	*38.00 FS
19	1		*SEALANT	Necessary	50.00 FS	*50.00 FS
20	1		*SUNDRY	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,675.04	1,750.07
- List Item Discount on L Items 20.00/20.00% (S\$)	1,021.81	262.81
Total Parts (S\$)	4,653.23	1,487.26

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM	New	80.00	40.00
2	TO DISMANTLE AND REFIT THE INNER COMPONENTS OF THE TAILGATE INTO NEW TAILGATE ,TEST WIPER MOTOR AND WATER ETC	New	120.00	50.00
3	TO DISMANTLE AND REFIT THE REAR WINDSCREEN	New	120.00	120.00
4	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING TO KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE OF THE END PANEL ETC	New	850.00	360.00
5	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER ,TAILGATE ,TAILGATE LOWER GARNISH ,END PANEL	New	800.00	360.00
6	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	40.00
Gross Labour Cost (S\$)			2,090.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >