

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EG121009298/UQF3E2

Date: 14/10/2021

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : YQ2657G

Insured Vehicle No : XD3863B

Date of Loss: 31/08/2021

Nature of Claim:

TP

Claim No: CDMCG21001696

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YQ2657G**

Make & Model: MITSUBISHI CANTER, 3.0 D FEB21ER4SDEN (M)

Engine No: 4P10E18106

Reg. Date: 28/08/2020 (Man. Year: 2020)

Chassis No: FEB21EA35072

Colour: Orange

Odometer: 53515 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15 (D)

Front Left Side: Austone 7 mm

Rear Left Side: Dunlop 7/7 mm

Front Right Side: Austone 7 mm

Rear Right Side: Dunlop 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	45,718.90	18,169.31	27,549.59	60.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,300.00	4,430.00	1,870.00	29.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	52,018.90	22,599.31	29,419.59	56.56
Approved Total (Overridden) (S\$)		18,000.00		
(S\$)	52,018.90	18,000.00	34,018.90	65.40
+ GST 7.00/7.00% (S\$)	3,641.32	1,260.00	2,381.32	65.40
Nett Amount (S\$)	55,660.22	19,260.00	36,400.22	65.40

INSPECTION

Date of Assignment: 03/09/2021

Date Inspected: 06/09/2021 Inspected At:

Liu's Brother Auto Workshop (HQ)

1 Kaki Bukit Ave 6 #01-01, Auto Bay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 20.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Oct 2021)	
Parts:	N/A	mitsubishi canter 3.0 d feb21er4sden (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ2657G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Bent	1,133.40 F	*1,133.40 FL
2	1	*SET FRONT BUMPER CLIPS	Not Necessary	50.00 F	*- FL
3	1	*FRONT BUMPER SIDE LH	Deformed	375.00 F	*304.15 FL
4	1	*SET FRONT BUMPER SIDE CLIPS	Not Necessary	45.00 F	*- FL
5	1	*FRONT BUMPER BRACKET LH	Repair	196.30 F	*- FL
6	1	*FRONT BUMPER SENSOR	Cracked / Damaged	1,970.00 F	*1,655.10 FL
7	1	*FRONT BUMPER SENSOR COVER	Damaged	490.00 F	*210.20 FL
8	1	*FRONT RADIATOR	Serviceable	3,122.30 F	*- FL
9	1	*FRONT RADIATOR RESERVOIR	Torn	98.50 F	*98.50 FL
10	1	*FRONT RADIATOR WATER PANEL	Cracked	563.80 F	*563.80 FL
11	1	*FRONT RADIATOR WATER HOSE	Dented	221.20 F	*221.20 FL
12	1	*FRONT RADIATOR FAN BLADE	Warped	225.50 F	*225.50 FL
13	1	*FRONT RADIATOR FAN COWLING	Cracked	496.30 F	*496.30 FL
14	1	*FRONT RADIATOR COOLANT	Not Necessary	50.00 F	*- FL
15	1	*FRONT HEAD LAMP LH	Cracked	856.40 F	*856.40 FL
16	1	*SET FRONT HEAD LAMP CLIPS	Not Necessary	30.00 F	*- FL
17	1	*FRONT GRILLE	Cracked	1,105.70 F	*685.10 FL
18	1	*SET FRONT GRILLE CLIPS	Not Necessary	30.00 F	*- FL
19	1	*FRONT GRILLE MITSUBISHI LOGO GRILLE	Necessary	187.00 F	*90.00 FL
20	1	*FRONT CANTER EMBLEM	Necessary	86.00 F	*75.70 FL
21	1	*FRONT CABIN BACK PANEL	Dented / Bent	1,997.00 F	*1,685.10 FL
22	1	*FRONT CABIN REAR GLASS RUBBER	Cut	266.20 F	*266.20 FL
23	1	*FRONT CABIN LOCK	Not Necessary	1,870.00 F	*- FL
24	1	*FRONT POWER STEERING OIL TANK	Torn	1,194.40 F	*485.00 FL
25	1	*FRONT AIR CLEANER ASSY	Cracked	826.90 F	*826.90 FL
26	1	*FRONT AIR CLEANER DUCT	Cut	488.50 F	*488.50 FL
27	2	*FRONT ENGINE MOUNTING	Not Necessary	396.60 F	*- FL
28	2	*FRONT GEARBOX MOUNTING	Not Necessary	354.40 F	*- FL
29	1	*FRONT THROTTLE BODY ASSY	Dented / Damaged	1,622.30 F	*1,622.30 FL
30	1	*FRONT EGR HOUSING	Damaged	645.30 F	*645.30 FL
31	1	*FRONT EGR VALVE PIPE	Damaged	295.00 F	*295.00 FL
32	1	*FRONT SENSOR, INLET MANIFOLD AIR TEMPERATURE	Cracked	680.50 F	*680.50 FL
33	1	*FRONT EXHAUST SENSOR PIPE	Damaged	392.80 F	*392.80 FL
34	1	*FRONT NUMBER PLATE METAL	Bent	28.00 FS	*14.00 FS
35	1	*FRONT TURBO UNIT	Not Necessary	6,171.80 F	*- FL
36	1	*FRONT TURBO WIRE	Torn	866.20 F	*866.20 FL
37	1	*FRONT TURBO WIRE INTAKE HOUSING	Damaged	750.00 F	*750.00 FL
38	1	*REAR CARGO BOX REAR DOOR	N/S Dented / O/S Repair	4,003.00 FS	*1,200.00 FS
39	1	*REAR CARGO BOX FRONT PANEL LOWER	Dented	1,600.00 FS	*900.00 FS
40	1	*REAR CARGO BOX LOWER PANEL OUTER	Dented	1,130.00 FS	*700.00 FS
41	1	*REAR CARGO LOWER PANEL INNER	Dented	1,670.00 FS	*700.00 FS
42	2	*REAR TAIL LAMP	Cracked	488.60 F	*488.60 FL
43	2	*REAR TAIL LAMP PANEL	Not Necessary	434.00 F	*- FL
44	1	*REAR CARGO BOX FLOOR BOARD LOWER	Cracked	2,340.00 FS	*1,000.00 FS

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*REAR CARGO BOX FLOOR BOARD TOP	Cracked	600.00 FS	*500.00 FS
46	1	*REAR SPRING LOCK CORNER SLIDING	Bent	250.00 FS	*100.00 FS
47	6	*REAR U CLIPS	Not Necessary	1,740.00 FS	*- FS
48	1	*REAR NUMBER PLATE METAL	Repeated	28.00 FS	*- FS
49	1	*REAR CORPORATE ADVERTISEMENET & ARTWORK	Necessary	451.00 FS	*300.00 FS
50	1	*FRONT ROCKER COVER TOP	Distorted	366.00 F	*366.00 FL
51	2	*REAR CARGO BOX BAR LOCK	Bent	440.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	45,718.90	22,287.75
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	4,118.44
Total Parts (\$\$)	45,718.90	18,169.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & LIFT UP CARGO BOX & REPLACING	New	800.00	500.00
2	LABOR FOR REPAIRING OF REAR CARGO BOX	New	1,800.00	1,600.00
3	TO REMOVE & REPLACE RADIATOR & CONDUCT PRESSURE TEST AND BLEED SYSTEM	New	180.00	50.00
4	TO DISMANTLE & REPLACING ENGINE PARTS & COMPONENTS	New	400.00	100.00
5	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	80.00	30.00
6	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	120.00	50.00
7	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS (FRONT)	New	1,200.00	1,000.00
8	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	1,600.00	1,100.00
9	TO REMOVE, REPLACE AND TRANSFER BOX DOORS PANEL, FITTING AND MECHANISMS	New	120.00	0.00
Gross Labour Cost (\$\$)			6,300.00	4,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >