

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21009301/KEA3Q2**Date:** 19/04/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	EV822U	Insured Vehicle No :	SLL8925Z
Date of Loss:	28/08/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003682

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EV822U	Engine No:	2GR0537379
Make & Model:	TOYOTA ESTIMA, 3.5 WELCAB 3.5G (A)	Chassis No:	GSR507016809
Reg. Date:	12/07/2008 (Man. Year: 2008)	Odometer:	64588 km
Colour:	Metallic Red		
Engine Capacity:	3456 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,418.40	0.00	1,418.40	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,090.00	470.00	620.00	56.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,508.40	470.00	2,038.40	81.26
Approved Total (Overridden) (\$\$)		370.00		
(\$\$)	2,508.40	370.00	2,138.40	85.25
+ GST 7.00/7.00% (\$\$)	175.59	25.90	149.69	85.25
Nett Amount (\$\$)	2,683.99	395.90	2,288.09	85.25
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	03/09/2021	
Date Inspected:	06/09/2021	Inspected At: Ricardo Auto Centre Pte Ltd (HQ) 160 Sin Ming Drive, #02-02, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	1.0 days	

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Apr 2022)
Parts:	M1-MPV	TOYOTA ESTIMA 3.5 WELCAB 3.5G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for EV822U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	*Check	682.80 F	*- FL
2	2		*FRONT BUMPER SIDE RETAINER RH & LH	Serviceable	229.40 F	*- FL
3	10		*FRONT BUMPER CLIPS	*Check	35.00 F	*- FL
4	1		*FRONT FENDER SHIELD RH	Serviceable	351.20 F	*- FL
5	1		*FRONT BUMPER SPONGE	Serviceable	120.00 F	*- FL
					Sub Total (S\$)	1,418.40 0.00
					- List Item Discount on L Items 0.00/25.00% (S\$)	0.00 0.00
					Total Parts (S\$)	1,418.40 0.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT ,WELD & STRAIGHTEN FRONT PORTION CAUSED BY ACCIDENT ,ADJUST & REPLACE DAMAGE PARTS	New	500.00	200.00
2	TO FOCUS ,HEADLAMP ,CHECK WIRING	New	30.00	20.00
3	TO SPRAY PAINT ON REPAIRED AREAS	New	500.00	250.00
4	COMPUTERISED WHEEL ALIGNMENT	New	60.00	0.00
Gross Labour Cost (\$\$)			1,090.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >