

Our Job Ref No : 305484703

Date : 02/09/21

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHD4799L

28/08/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: CHINA SGU5874T

2. The finalized amount shall be:

(a) Spare Parts after List discount \$801.12

(b) Labour Charges \$660.00

Total for Part-By-Part Repair Cost \$1,461.12

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature :

Name : Thevan

Date : 7/9/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD4799L

28/08/21

MAKE 16.01.2020

MODEL IONIQ G3

CHIANG/CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$459.40
1	REAR BUMPER CENTRE MOULDING			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
2	REAR BUMPER STAY LH /RH		\$138.10	\$276.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER TOW COVER			\$98.80
1	REAR BUMPER FOG LAMP			\$201.50
2	REAR BUMPER BRACKET LH/RH		\$55.80	\$111.60
				\$2,015.55
				20.00%
				\$403.11
				DISCOUNTED TOTAL
				\$1,612.44
1	REAR NUMBER PLATE W/HOLDER			\$55.00
1	REAR REVERSE SENSOR			\$180.00
				\$235.00
	Labour Charge			
	Panel Beating			\$600.00
	Spray Painting Charge			\$300.00
	Tuff Kote			\$60.00
	Remove/Refix reverse sensor			\$60.00
				TOTAL LABOUR
				\$1,020.00
				+
				ESTIMATE TOTAL
				\$2,867.44
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Thavan Lkh
82235769
thavan@lkhauto.com
2 days wp
P/P bfr paint photos
30/8/21 1715

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305484703
 REGN NO : SHD4799L
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 16.01.2020
 DATE/TIME IN : 30.08.2021 09:50
 ACCIDENT DATE : 28.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	/cut
0002 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	/ncc
0003 28-01-0104-2029-A	VEHICLE NUMBER PLATE REAR	1	55.00	2.00-	55.00	/scr
0004 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	/DEF
						SUB-TOTAL : 801.12

JOB NATURE

0000 PB	PANEL BEATING-SHD4799L	350.00
0001 SP	SPRAYPAINT CHARGE	250.00
0002 20-00	TUFF COAT ON AFFECTED PARTS.	30.00
0003 20-22	REMOVE/REFIX REVERSE SENSOR	30.00
		SUB-TOTAL : 660.00

Total: 1461.12

2bs