

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21009309/AEA3Q2**Date:** 13/01/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SKS6848B**Insured Vehicle No :** SGS7077A

Date of Loss: 02/09/2021

Nature of Claim: TP

Claim No: 0445838052SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKS6848B**

Make & Model: VOLKSWAGEN JETTA TSI, 1.4 (A)

Engine No: CAXE89399

Reg. Date: 29/04/2015 (Man. Year: 2014)

Chassis No: WVVZZZ16ZEM063928

Colour: White

Odometer: 117315 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	49,013.86	36,129.60	12,884.26	26.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,470.00	5,000.00	5,470.00	52.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	59,483.86	41,129.60	18,354.26	30.86
Approved Total (Overridden) (S\$)		13,500.00		
(S\$)	59,483.86	13,500.00	45,983.86	77.30
+ GST 7.00/7.00% (S\$)	4,163.87	945.00	3,218.87	77.30
Nett Amount (S\$)	63,647.73	14,445.00	49,202.73	77.30
+ Loss of Use (21.0 x S\$60.00/day) (S\$)		1,260.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		15,707.00		
Global Sum Settlement (S\$)		15,700.00		

INSPECTION

Date of Assignment: 02/09/2021

Date Inspected: 02/09/2021 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Estimated Period of Repair: 18.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	1,120.00 FL	*1,120.00 FL
2	1		*FRONT BONNET LOCK	Damaged	209.30 FL	*209.30 FL
3	1		*FRONT BONNET LOCK CATCH	Not Necessary	91.80 FL	*- FL
4	1		*FRONT BONNET LOCK CABLE	Not Necessary	42.80 FL	*- FL
5	2		*FRONT BONNET HINGE	Bent	173.00 FL	*173.00 FL
6	1		*FRONT BONNET ABSORBER	Not Necessary	126.50 FL	*- FL
7	1		*FRONT BONNET INSULATOR	Crumpled	392.10 FL	*392.10 FL
8	1		*FRONT BONNET SEAL	Not Necessary	32.50 FL	*- FL
9	1		*FRONT BONNET STOPPER	Not Necessary	37.40 FL	*- FL
10	2		*FRONT FENDER	Buckled	1,159.20 FL	*1,159.20 FL
11	2		*FRONT FENDER COWLING	Not Necessary	584.20 FL	*- FL
12	2		*HEAD LAMP	Cracked	3,381.20 FL	*3,381.20 FL
13	1		*RADIATOR GRILLE	Cracked	551.50 FL	*551.50 FL
14	1		*RADIATOR GRILLE EMBLEM	Necessary	148.75 FL	*148.75 FL
15	1		*FRONT BUMPER	Distorted	1,348.40 FL	*1,348.40 FL
16	2		*FRONT BUMPER RETAINER	Not Necessary	314.20 FL	*- FL
17	1		*FRONT BUMPER REINFORCEMENT	Dented	762.50 FL	*762.50 FL
18	1		*FRONT BUMPER ABSORBER	Cracked	278.75 FL	*278.75 FL
19	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	862.50 FL	*- FL
20	1		*FRONT NUMBER PLATE GARNISH	Cracked	143.10 FL	*143.10 FL
21	2		*FRONT FOG LAMP COVER	Not Necessary	150.20 FL	*- FL
22	1		*FRONT SUPPORT PANEL	Cracked	1,151.50 FL	*1,151.50 FL
23	2		*FRONT HEAD LAMP PANEL	Buckled	112.40 FL	*112.40 FL
24	1		*AIRCON CONDENSER ASSY	Dented	756.25 FL	*756.25 FL
25	1		*RADIATOR ASSY	Dented	712.50 FL	*712.50 FL
26	1		*RADIATOR FAN COWLING	Not Necessary	240.90 FL	*- FL
27	1		*RADIATOR FAN MOTOR ASSY	Not Necessary	1,653.00 FL	*- FL
28	1		*WATER COOLER	Dented	846.50 FL	*846.50 FL
29	1		*RADIATOR TANK	Not Necessary	160.00 FL	*- FL
30	1		*RADIATOR TOP HOSE	Not Necessary	162.80 FL	*- FL
31	1		*AIR CLEANER BOX ASSY	Cracked	435.00 FL	*435.00 FL
32	1		*DRIVER AIR BAG	Activated	3,553.85 FL	*3,553.85 FL
33	1		*DRIVER AIR BAG SPIRAL WIRE	Activated	1,031.25 FL	*1,031.25 FL
34	1		*FRONT PASSANGER AIR BAG	Activated	3,260.00 FL	*3,260.00 FL
35	1		*AIR BAG MODULE (ECU)	Activated	2,670.40 FL	*2,670.40 FL
36	1		*FRONT DASHBOARD	Torn	3,344.00 FL	*3,344.00 FL
37	1		*FRONT SAFETY BELT	Activated	2,940.00 FL	*2,940.00 FL
38	1		*FRONT SAFETY BELT BUCKLE	Not Necessary	1,300.00 FL	*- FL
39	1		*FRONT WINDSCREEN GLASS	Cracked	1,460.00 FL	*1,460.00 FL
40	1		*REAR BOOT LID	Distorted	1,459.70 FL	*1,459.70 FL
41	1		*REAR BOOT LID HINGE	Not Necessary	452.60 FL	*- FL
42	1		*REAR BOOT LID INNER LOCK	Damaged	180.90 FL	*180.90 FL
43	1		*REAR BOOT LID INNER BOARD	Not Necessary	294.40 FL	*- FL
44	1		*REAR BOOT LID LOGO	Necessary	189.30 FL	*189.30 FL
45	1		*REAR BOOT LID EMBLEM (JETTA)	Necessary	68.10 FL	*68.10 FL
46	1		*REAR BOOT LID EMBLEM (ISI)	Necessary	52.30 FL	*52.30 FL
47	2		*REAR BOOT LID LAMP	Cracked	516.20 FL	*516.20 FL
48	2		*TAIL LAMP	Cracked	837.60 FL	*837.60 FL
49	2		*REAR FENDER	Repair	3,421.80 FL	*- FL
50	2		*REAR FENDER INNER GARNISH	Not Necessary	603.80 FL	*- FL
51	2		*REAR TAIL LAMP PANEL	Repair	608.00 FL	*- FL
52	1		*REAR BUMPER DIFFUSE	Deformed	455.70 FL	*455.70 FL
53	1		*REAR BUMPER	Distorted	1,806.20 FL	*1,806.20 FL
54	1		*REAR BUMPER TOWING COVER	Deformed	34.70 FL	*34.70 FL
55	1		*REAR BUMPER REINFORCEMENT	Dented	354.70 FL	*354.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*REAR BUMPER CENTRE RETAINER	Cracked	89.10 FL	*89.10 FL
57	2		*REAR BUMPER RETAIN	Necessary	99.40 FL	*99.40 FL
58	2		*REAR BUMPER REFLECTOR	Not Necessary	84.20 FL	*- FL
59	2		*REAR NUMBER LAMP	Not Necessary	71.20 FL	*- FL
60	1		*END PANEL OUTER	Distorted	765.60 FL	*765.60 FL
61	1		*END PANEL INNER	Repair	517.20 FL	*- FL
62	1		*END PANEL GARNISH	Deformed	506.20 FL	*506.20 FL
63	1		*SARE TYRE PANEL	Repair	1,095.30 FL	*- FL
64	1		*SARE TYRE PANEL COVER BOARD	Deformed	581.30 FL	*581.30 FL
65	1		*REAR EXHAUST PIPE	Not Necessary	1,106.30 FL	*- FL
66	1		*REAR EXHAUST PIPE HEAT SHIELD	Not Necessary	143.40 FL	*- FL
67	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	114.40 FL	*- FL
68	1		*FRONT NUMBER PLATE	Damaged	45.00 FS	*45.00 FS
69	1		*REAR NUMBER PLATE	Damaged	45.00 FS	*45.00 FS
70	1		*FRONT IU BRACKET	Necessary	35.00 FS	*35.00 FS
71	1		*SET FRONT WINDSCREEN GLASS SEALANT	Necessary	100.00 FS	*60.00 FS
					Sub Total (\$\$)	54,434.85
					- List Item Discount on L Items 10.00/10.00% (\$\$)	5,420.99
					Total Parts (\$\$)	49,013.86

40,123.45

3,993.85

36,129.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET	New	650.00	200.00
2	TUFF KOTE	New	350.00	80.00
3	REMOVE AND REPLACE AIRCON CONDENSER & REFILL GAS	New	250.00	60.00
4	REMOVE AND REPLACE RADIATOR	New	100.00	60.00
5	REMOVE AND REPLACE FRONT WINDSCREEN	New	160.00	120.00
6	REMOVE AND REPLACE DASHBOARD	New	450.00	220.00
7	REMOVE AND REFIX UPHOLSTERY	New	160.00	80.00
8	REMOVE AND REPLACE AIR BAG	New	550.00	380.00
9	TO REMOVE AND REPLACE SPARE PART AND PANEL BEATING	New	4,800.00	2,000.00
10	TO SPRAY PAINT AFFECTED PORTION	New	3,000.00	1,800.00
Gross Labour Cost (\$\$)			10,470.00	5,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >