

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21009310/BGS3Q2
Date: 19/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	FBS3360S	Insured Vehicle No :	SJL9920D
Date of Loss:	26/08/2021	Nature of Claim:	TP
		Claim No:	3682913653SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBS3360S		
Make & Model:	YAMAHA NMAX155, 155cc	Engine No:	G3L8E0475152
Reg. Date:	26/03/2021 (Man. Year: 2021)	Chassis No:	MH3SG5680MK070201
Colour:	Black	Odometer:	0 km
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110/70/13	Rear Tyre Size:	130/70/13
Front Left Side:	IRC 6 mm	Rear Left Side:	IRC 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,185.52	2,745.74	5,439.78	66.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,250.00	700.00	550.00	44.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,435.52	3,445.74	5,989.78	63.48
Approved Total (Overridden) (S\$)		2,750.00		

Nett Amount (S\$)	9,435.52	2,750.00	6,685.52	70.85
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 05/09/2021

Date Inspected: 07/09/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Accident Assist SG (HQ)
24 Sin Ming Lane, #01-94 Mid View City
Singapore 573970

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	194.20 FL	*194.20 FL
2	1		*SET HANDLE BAR BRACKET	Necessary	92.50 FL	*92.50 FL
3	1		*SET HANDLE GRIP	Not Necessary	76.00 FL	*- FL
4	1		*SET HANDLE BALANCER	Cut	84.00 FL	*60.00 FL
5	1		*SET REAR VIEW MIRROR	Cut	95.00 FL	*95.00 FL
6	1		*REAR BRAKE LEVER	Cut	92.70 FL	*41.00 FL
7	1		*STEERING STEM	Not Damaged	582.00 FL	*- FL
8	2		*FRONT FORK	Not Damaged	1,828.50 FL	*- FL
9	1		*FRONT FORK BRACKET	Not Damaged	559.20 FL	*- FL
10	1		*FRONT DISC ROTOR	Not Damaged	169.30 FL	*- FL
11	1		*FRONT BRAKE CALIPER	Not Damaged	253.70 FL	*- FL
12	1		*FRONT RIM	Not Damaged	820.00 FL	*- FL
13	1		*FRONT RIM SHAFT	Not Necessary	78.00 FL	*- FL
14	1		*FRONT FENDER	Cut	183.50 FL	*183.50 FL
15	1		*FRONT SIGNAL LIGHT LH	Not Damaged	89.00 FL	*- FL
16	1		*FRONT SIDE FAIRING LH	Cut	193.80 FL	*193.80 FL
17	1		*FRONT SIDE LEG SHIELD COWLING LH	Cut	145.00 FL	*145.00 FL
18	1		*FRONT SIDE LEG SHIELD COWLING EMBLEM LH	Necessary	45.00 FL	*45.00 FL
19	1		*SIDE FAIRING LOWER LH	Cut	132.50 FL	*132.50 FL
20	1		*SIDE FAIRING CENTRE LH	Cut	155.00 FL	*155.00 FL
21	1		*FRONT FOOTREST BOARD LH	Not Damaged	142.40 FL	*- FL
22	1		*REAR FOOTREST LH	Cut	96.50 FL	*70.00 FL
23	1		*REAR SIDE FAIRING LH	Cut	178.00 FL	*178.00 FL
24	1		*REAR SIDE FAIRING EMBLEM LH	Necessary	90.00 FL	*60.00 FL
25	1		*REAR SIDE COWLING LH	Cut	75.00 FL	*75.00 FL
26	1		*SIDE STAND	Cut	69.30 FL	*69.30 FL
27	1		*MAIN STAND	Cut	177.00 FL	*147.80 FL
28	1		*HEADLIGHT	Cut	752.70 FL	*520.00 FL
29	1		*HEADLIGHT STAY	Not Damaged	84.00 FL	*- FL
30	1		*TAILLIGHT	Broken	569.00 FL	*285.00 FL
31	1		*AIR FILTER OUTER COVER	Cut	82.00 FL	*82.00 FL
32	1		*CRANK PULLEY COVER	Cut	132.00 FL	*132.00 FL
33	1		*EXHAUST MUFFLER PROTECTOR	Cut	72.00 FL	*72.00 FL
34	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
35	1		*REAR NUMBER PLATE	Bent	40.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*STEERING CONE BEARING	Not Necessary	60.00 FS	*- FS
37	1		*FRONT FORK OIL	Not Necessary	68.00 FS	*- FS
38	1		*FRONT TYRE	Not Damaged	110.00 FS	*- FS
39	1		*SET FRONT FOOTREST FLOOR MATS (ACCESSORIES)	Not Necessary	187.60 FS	*- FS
40	1		*REAR TYRE	Not Damaged	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,024.40	3,048.60
- List Item Discount on L Items 10.00/10.00% (\$)	838.88	302.86
Total Parts (\$)	8,185.52	2,745.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE /REPLACE DAMAGED PARTS & COMPONENTS	New	400.00	300.00
2	TO CARRY OUT BODY FRAME ALIGNMENT	New	350.00	0.00
3	TO RESPRAY REPLACED & AFFECTED PARTS	New	500.00	400.00
Gross Labour Cost (\$\$)			1,250.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >