

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009312/DTCN2**Date:** 20/12/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00075712100

Claimant Vehicle No : SMN6634D **Insured Vehicle No :** SKB1015K

Date of Loss: 02/09/2021 Nature of Claim: TP Claim No: SNM21D204965/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN6634D**

Make & Model: AUDI A3, 999cc TFSI S TRONIC (LED) (A) Engine No: CHZC31329

Reg. Date: 22/08/2019 (Man. Year: 2019) Chassis No: WAUZZZ8V6KA099337

Colour: Black Odometer: 22293 km

Engine Capacity: 999 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R18 Rear Tyre Size: 225/40R18

Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,724.94	14,858.71	17,866.23	54.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,020.00	2,010.00	4,010.00	66.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	38,744.94	16,868.71	21,876.23	56.46
Approved Total (Overridden) (\$\$)		13,500.00		
(\$\$)	38,744.94	13,500.00	25,244.94	65.16
+ GST 7.00/7.00% (\$\$)	2,712.15	945.00	1,767.15	65.16
Nett Amount (\$\$)	41,457.09	14,445.00	27,012.09	65.16

INSPECTION

Date of Assignment: 07/09/2021

Date Inspected: 06/09/2021 Inspected At: C S Ong Motor (HQ)
BLK 10 ANG MO KIO IND PARK 2A #04-01 AMK
AUTO POINT
Singapore 568047

Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Dec 2021)
Parts:	144	AUDI A3 999cc TFSI S TRONIC (LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN6634D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP RH	Mounting Broken	9,892.00 FL	*4,967.95 FL
2	1		*HEAD LAMP LOWER BRACKET RH	Repair	250.00 FL	*- FL
3	1		*FRONT FENDER RH	Dented	1,672.00 FL	*680.40 FL
4	1		*FRONT FENDER INNER SHIELD RH	Deformed	201.00 FL	*201.00 FL
5	1		*FRONT WHEEL BEARING RH	Damaged	395.00 FL	*395.00 FL
6	1		*FRONT WHEEL BEARING HUB RH	No such part	499.00 FL	*- FL
7	1		*FRONT KNUCKLE ARM RH	Distorted	1,239.00 FL	*968.00 FL
8	1		*FRONT LOWER ARM RH	Distorted	785.00 FL	*615.00 FL
9	1		*FRONT UPPER ARM RH	Not Necessary	699.00 FL	*- FL
10	1		*FRONT CONTROL ARM RH	Not Necessary	592.00 FL	*- FL
11	1		*FRONT THRUST ARM RH	Not Necessary	782.00 FL	*- FL
12	1		*FRONT ABSORBER RH	Distorted	1,164.00 FL	*680.00 FL
13	1		*FRONT STABILIZER LINK RH	Bent	359.00 FL	*205.65 FL
14	1		*FRONT STABILIZER BAR	Not Necessary	510.00 FL	*- FL
15	1		*FRONT TIE ROD RH	Not Necessary	310.00 FL	*- FL
16	1		*FRONT TIE ROD END RH	Not Necessary	882.00 FL	*- FL
17	1		*STEERING RACK & PINION ASSY	Damaged	3,886.55 FL	*3,886.55 FL
18	1		*DRIVE SHAFT RH	Not Necessary	2,492.00 FL	*- FL
19	1		*FRONT BUMPER	Dented	2,015.00 FL	*2,015.00 FL
20	1		*FRONT BUMPER SIDE RETAINER RH	Cracked	184.00 FL	*96.30 FL
21	1		*FRONT BUMPER FOG LAMP GARNISH RH	Mounting Broken	310.00 FL	*160.50 FL
22	1		*FRONT BUMPER FOG LAMP CHROME MOULDING RH	No such part	194.00 FL	*- FL
23	1		*FRONT DOOR RH	Repair	2,894.50 FL	*- FL
24	1		*FRONT DOOR WINDOW MOULDING RH	Not Necessary	349.00 FL	*- FL
25	1		*FRONT BUMPER UNDERCOVER	Mounting Cracked	471.66 FL	*471.66 FL
26	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
27	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
28	1		*FRONT BUMPER FOG LAMP GARNISH CLIPS	Necessary	50.00 FS	*15.00 FS
29	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*15.00 FS
30	1		*SPORT RIM	Cut	2,000.00 FS	*1,000.00 FS
31	1		*TYRE	Not Necessary	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	36,027.71	16,393.01
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,302.77	1,534.30
Total Parts (\$\$)	32,724.94	14,858.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	800.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	800.00
3	TO TUFF COAT DAMAGED AREAS	New	200.00	20.00
4	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	New	400.00	150.00
5	TO CONDUT COMPUTERIZED WHEEL ALIGNMENT	New	120.00	60.00
6	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
7	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	150.00
Gross Labour Cost (S\$)			6,020.00	2,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >