



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 4619S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	FRONT FORK TUBE ASSY (CONSISTENT)	SERVICEABLE	640.00	-
1	FORK UNDER BRACKET (CONSISTENT)	SERVICEABLE	185.00	-
1	PILOT LIGHT (CONSISTENT)	SCRATCHED	120.00	120.00
1	HORN COVER INNER (CONSISTENT)	NOT NECESSARY	80.00	-
1	FRONT WHEEL RIM (CONSISTENT)	CUT	280.00	280.00
1	FRONT RIM SHAFT (CONSISTENT)	CUT	45.00	45.00
1	FRONT RIM BEARING (CONSISTENT)	NECESSARY	38.00	38.00
1	FRONT BRAKE DISC (CONSISTENT)	NOT NECESSARY	155.00	-
1	HANDLE BAR (CONSISTENT)	BENT	88.00	88.00
1	HANDLE BAR END - R/H (CONSISTENT)	SERVICEABLE	32.00	-
1	SET HAND GRIP (CONSISTENT)	NOT NECESSARY	55.00	-
2	SIDE MIRRORS (CONSISTENT)	N/S CUT	110.00	50.00
1	CLUTCH LEVER (CONSISTENT)	SCRATCHED	32.00	32.00
1	FRONT SIGNAL - L/H (CONSISTENT)	SCRATCHED	80.00	45.00
1	SET FAIRING ASSY (CONSISTENT)	CUT	495.00	495.00
1	SET FRONT FOOTREST (CONSISTENT)	CUT	158.00	110.00
1	SET FRONT FOOTREST BRACKET (CONSISTENT)	BENT	130.00	130.00
1	GEAR PEDAL (CONSISTENT)	BENT	35.00	35.00
1	REAR FOOTREST - L/H (CONSISTENT)	NOT NECESSARY	42.00	-
1	REAR FOOTREST BRACKET (CONSISTENT)	NOT NECESSARY	40.00	-
1	REAR SIGNAL - L/H (CONSISTENT)	NOT NECESSARY	70.00	-
	LESS 10% DISCOUNT		-291.00	-146.80
			2,619.00	1,321.20
<u>SPECIAL NETT ITEMS</u>				
1	SET NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	38.00	-
2	FORK OILS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN) (CONSISTENT)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN) (CONSISTENT)	NOT NECESSARY	98.00	-
1	REAR BOX (SN) (CONSISTENT)	NOT NECESSARY	480.00	-
1	REAR BOX BRACKET (SN) (CONSISTENT)	NOT NECESSARY	180.00	-

Report Ref No. CS/ASM21009314/Uvce2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET STICKER (SN) (CONSISTENT)	NECESSARY	120.00	120.00
			1,002.00	120.00
	LABOUR			
	TO PROVIDE TOWING SERVICE. (NPA)	NOT NECESSARY	-	-
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR.		380.00	250.00
	TO REPAIR BODY FRAME.	NOT NECESSARY	350.00	-
			810.00	250.00
GRAND TOTAL			4,431.00	1,691.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,300.00

Report Ref No. CS/ASM21009314/Uvce2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.