

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009320/GNCQ2**Date:** 23/11/2022REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00023612100

**Claimant Vehicle
No :** SMW5801Y**Insured Vehicle
No :** SLJ8663P

Date of Loss: 02/09/2021

Nature of Claim: TP

Claim
No: SNM21D204967/C02/TANKWDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMW5801Y**

Make & Model: SEAT ARONA, 999cc FR 1.0 TSI 116 7AT (A)

Engine No: DKJ041060

Reg. Date: 27/11/2020 (Man. Year: 2019)

Chassis No: VSSZZKJZKR156725

Colour: Grey

Odometer: 25737 km

Engine Capacity: 999 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17

Rear Tyre Size: 205/55 R17

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,703.70	9,851.10	22,852.60	69.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,450.00	1,950.00	5,500.00	73.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	40,153.70	11,801.10	28,352.60	70.61
Approved Total (Overridden) (\$\$)		9,350.00		
(\$\$)	40,153.70	9,350.00	30,803.70	76.71
+ GST 7.00/7.00% (\$\$)	2,810.76	654.50	2,156.26	76.71
Nett Amount (\$\$)	42,964.46	10,004.50	32,959.96	76.71

INSPECTION

Date of Assignment: 08/09/2021

Date Inspected: 07/09/2021 Inspected At:

56 LOYANG WAY, #04-04 LOYANG ENTERPRISE
BUILDING

Repairer: AP Automotive Services Pte Ltd (HQ)

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Nov 2022)
Parts:	144	SEAT ARONA 999cc FR 1.0 TSI 116 7AT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW5801Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	2,119.00 FL	*2,119.00 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Not Necessary	270.00 FL	*- FL
3	2		*TAILGATE LAMP L+R	Not Necessary	2,198.00 FL	*- FL
4	1		*TAILGATE HANDLE SWITCH	Not Necessary	204.00 FL	*- FL
5	2		*TAILGATE NUMBER PLATE L+R	Not Necessary	164.00 FL	*- FL
6	1		*TAILGATE LOGO -SEAT	Necessary	99.00 FL	*99.00 FL
7	1		*TAILGATE EMBLEM -ARONA	Necessary	407.00 FL	*80.00 FL
8	1		*TAILGATE EMBLEM -FR	Necessary	97.00 FL	*97.00 FL
9	1		*TAILGATE LOCK	Not Necessary	596.00 FL	*- FL
10	1		*TAILGATE LOCK CATCH	Not Necessary	79.00 FL	*- FL
11	2		*TAILGATE HINGE L+R	Not Necessary	258.00 FL	*- FL
12	2		*TAILGATE DAMPER L+R	Not Necessary	670.00 FL	*- FL
13	1		*TAILGATE INNER BOARD	Broken	1,071.00 FL	*305.00 FL
14	1		*TAILGATE WEATHERSTRIP	Torn	450.00 FL	*285.00 FL
15	2		*TAIL LAMP L+R	Broken	3,340.00 FL	*1,280.00 FL
16	2		*TAIL LAMP BRACKET L+R	Broken	288.00 FL	*120.00 FL
17	1		*REAR BUMPER	Deformed	1,704.00 FL	*1,400.00 FL
18	4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	1,840.00 FL	*380.00 FL
19	2		*REAR BUMPER REFLECTOR L+R	Broken	880.00 FL	*100.00 FL
20	1		*REAR BUMPER LOWER	Cut	970.00 FL	*650.00 FL
21	1		*REAR BUMPER LOWER DIFFUSOR	Cut	800.00 FL	*550.00 FL
22	1		*REAR BUMPER LOWER DIFFUSOR TOW COVER	Cut	59.00 FL	*55.00 FL
23	2		*REAR BUMPER RETAINER L+R	Broken	284.00 FL	*120.00 FL
24	1		*REAR BUMPER REINFORCEMENT BAR	Bent	916.00 FL	*620.00 FL
25	1		*REAR BUMPER SPONGE (NPA)	Not Necessary	0.00 FL	*- FL
26	1		*REAR BUMPER UNDERCOVER	Broken	649.00 FL	*105.00 FL
27	1		*REAR FENDER INNER TRIM L+R	O/S Torn / N/S Not Necessary	1,740.00 FL	*305.00 FL
28	2		*REAR FENDER COWLING L+R	Not Necessary	676.00 FL	*- FL
29	2		*REAR WHEEL ARC PROTECTOR L+R	Not Necessary	804.00 FL	*- FL
30	1		*END PANEL	Buckled	1,041.00 FL	*815.00 FL
31	1		*END PANEL TOP GARNISH	Broken	376.00 FL	*289.00 FL
32	1		*REAR SMART LOCK ANTENNA	Damaged	570.00 FL	*250.00 FL
33	1		*FLOOR PANEL	Repair	1,789.00 FL	*- FL
34	1		*FLOOR PANEL TOP BOARD	Not Necessary	1,509.00 FL	*- FL
35	1		*FLOOR PANEL ACCESSORIES BOX	Not Necessary	509.00 FL	*- FL
36	2		*FLOOR PANEL TOOLS SPONGE L+R	Not Necessary	442.00 FL	*- FL
37	1		*EXHAUST PIPE	Not Necessary	1,044.00 FL	*- FL
38	2		*EXHAUST CHROME TIP L+R	Broken	1,004.00 FL	*200.00 FL
39	2		*EXHAUST MOUNTING	Not Necessary	291.00 FL	*- FL
40	1		*EXHAUST HEAT SHIELD	Not Necessary	307.00 FL	*- FL
41	1		*REAR BUMPER CENTER BRACKET	Broken	205.00 FL	*205.00 FL
42	1		*PRASIMITY SENSOR	Damaged	1,074.00 FL	*350.00 FL

Report was unsubmitted during this print-out.

11/23/22, 11:53 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*TAILGATE WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
44	1		*TAILGATE INNER TRIM CLIPS	Necessary	100.00 FS	*30.00 FS
45	1		*REVERSE CAMERA	Not Necessary	800.00 FS	*- FS
46	1		*REAR NUMBER PLATE	Not Necessary	120.00 FS	*- FS
47	1		*TAIL LAMP CLIP	Not Necessary	50.00 FS	*- FS
48	1		*REAR BUMPER CLIP	Necessary	100.00 FS	*40.00 FS
49	1		*REAR SIDE BUMPER CLIP	Not Necessary	100.00 FS	*- FS
50	1		*REAR FENDER COWLING CLIP	Not Necessary	200.00 FS	*- FS
51	1		*REAR WHEEL ARC PROTECTOR CLIP	Not Necessary	200.00 FS	*- FS
52	1		*END PANEL SEALANT	Necessary	200.00 FS	*40.00 FS
53	1		*FLOOR PANEL SEALANT	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					36,083.00	10,929.00
- List Item Discount on L Items 10.00/10.00% (S\$)					3,379.30	1,077.90
Total Parts (S\$)					32,703.70	9,851.10
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	2,600.00	900.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,800.00	800.00
3	TO RNR REAR EXHAUST	New	400.00	0.00
4	TO CHECK WIRING AND TAIL LAMP FUNCTION	New	150.00	30.00
5	TO CHECK WIRING AND TAILGATE LAMP FUNCTION	New	150.00	0.00
6	TO RNR REAR TRIM AND UPHOLSTERY	New	400.00	60.00
7	TO CHECK WATER LEAK	New	150.00	0.00
8	TO RNR FUEL TANK	New	250.00	0.00
9	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
10	TO RNR REAR TAILGATE MECHANISM	New	400.00	60.00
11	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	40.00
12	TO PERFORM RUST PROOFING	New	400.00	60.00
Gross Labour Cost (\$\$)			7,450.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >