LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21009326/BTF3E2

Date: 30/11/2021

REFERENCE

No: FBH2342J Insured Vehicle No: SKL3889P

Date of Loss: 18/08/2021 Nature of Claim: TP Claim No: 9329007633SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBH2342J

Make & Model:PIAGGIO XEVO, 125ccEngine No:HIDDENReg. Date:15/04/2013 (Man. Year: 2013)Chassis No:HIDDENColour:BlackOdometer:82229 km

Engine Capacity: 125 cc
Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70/14 Rear Tyre Size: 130/70/13
Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 06/09/2021

At Assure Motoring (HQ)

Date Inspected: 06/09/2021 Inspected At: Blk 5032 Ang Mo Kio Industrial Park 2, #01-307

Singapore 569535

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$5,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Broken	0.00 F	*-F
2	2		*FRONT FORK ASSY	Bent	0.00 F	*- F
3	2		*FRONT FORK OIL SEAL	Necessary	0.00 F	*- F
4	1		*FRONT HEADLAMP	Broken	0.00 F	*- F
5	1		*FRONT HEADLAMP FAIRING	Broken	0.00 F	*- F
6	1		*FRONT WINDSHIELD	Cut	0.00 F	*- F
7	2		*FRONT WING MIRROR	Dislodged / Missing	0.00 F	*- F
8	1		*FRONT RH SIGNAL LAMP	Broken	0.00 F	*- F
9	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F
10	1		*HANDLE BAR BALANCER RH	Cut	0.00 F	*- F
11	1		*CLUTCH LEVER	Cut	0.00 F	*- F
12	1		*HAND BRAKE LEVER	Bent	0.00 F	*- F
13	1		*SIDE FAIRING	Cut	0.00 F	*- F
14	1		*SIDE FAIRING TOP GARNISH	Cut	0.00 F	*- F
15	1		*CENTER FAIRING	Cut	0.00 F	*- F
16	1		*REAR FAIRING	Cut	0.00 F	*- F
17	1		*FAIRING LOWER	Cut	0.00 F	*- F
18	1		*EXHAUST MUFFLER HEAT SHIELD	Cut	0.00 F	*- F
19	1		*REAR BOX	Cut	0.00 F	*- F
20	1		*EMBLEM	Necessary	0.00 F	*-F
F=Fra	anchise p	oart.		_		
				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >