



Your Ref : SNM21D204975/C02/TANCHC

Date: 10<sup>th</sup> Sep 2021

Our Ref : CS/CTI21009330/Atce2

**M/s China Taiping Insurance (S) Pte Ltd**

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SGR 4283X  
INSURED VEHICLE: SLQ 8368E  
ACCIDENT ON 02/09/2021**

Instruction was received to inspect the vehicle Reg. No. SGR 4283X. The inspection was conducted on 06/09/2021 at the premises of M/s N-51 Automotive Pte Ltd, Blk 2 Kaki Bukit, #01-17/18 Kaki Bukit Autohub, Singapore 417921.

The following vehicle information was recorded:

Registration Number	: SGR 4283X
Make/Model	: Nissan Sylphy 1.5 4AT
Year of Registration	: 2006
Body Colour	: Black
Chassis Number	: JN1BAAG11Z0100789
Engine Capacity	: 1498 cc

The vehicle sustained damages at the rear portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 4,500.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 2,114.00)
Nett Liability	<u>S\$ 2,386.00</u> =====

Vehicle Inspected By:



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser



K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK),

MASME(USA), B Bus(Aust),MBA(UK),

IEng(UK), MIE(mech), MinstAEA, MFIEA,

MIRTE,MIMI,MSAE,MCIAd, AM,NIJAAR(USA),

AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.