

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21009331/ETF3E2

Date: 06/10/2021

REFERENCE

Insured/Claimant:	MAZLAN BIN RAKIMAN	Policy No:	7210030818		
Date of Loss:	04/09/2021	Nature of Claim:	OD	Claim No:	3874305146SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGS4242J		
Make & Model:	MAZDA OUTLANDER, 2.0 (A)	Engine No:	4J11DA5541
Reg. Date:	26/03/2021 (Man. Year: 2020)	Chassis No:	GF7W0701101
Colour:	Silver	Odometer:	8011 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$115,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,635.00	7,431.97	6,203.03	45.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,480.00	6,090.00	1,390.00	18.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,115.00	13,521.97	7,593.03	35.96
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	20,815.00	13,221.97	7,593.03	36.48
+ GST 7.00/7.00% (S\$)	1,457.05	925.54	531.51	36.48
Nett Amount (S\$)	22,272.05	14,147.51	8,124.54	36.48

INSPECTION

Date of Assignment:	06/09/2021	
Date Inspected:	06/09/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	15.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH FRAME	Broken	50.00 FS	*50.00 FS
2	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
3	1		*FACE, FR BUMPER	Broken	863.00 F	*863.00 FL
4	1		*EXTENSION, FR BUMPER	Broken	517.00 F	*517.00 FL
5	1		*BRACKET, FR BUMPER SIDE, RH	Broken	18.00 F	*18.00 FL
6	1		*BRACKET, FR BUMPER SIDE, LH	Broken	18.00 F	*18.00 FL
7	1		*GARNISH, FR BUMPER, LH	Cut	48.00 F	*48.00 FL
8	1		*BRKT, FR BUMPER SIDE, LWR LH	Missing	6.00 F	*6.00 FL
9	1		*MOULDING, FR BUMPER, LH	Missing	97.00 F	*97.00 FL
10	1		*MOULDING, FR WHEEL ARCH, LH	Missing	168.00 F	*168.00 FL
11	1		*REINFORCEMENT, FR BUMPER	Bent	510.00 F	*510.00 FL
12	1		*REINF, F/BMPR SIDE, LWRLH	Bent	25.00 F	*25.00 FL
13	1		*REINFORCEMENT, FR BUMPER	Bent	135.00 F	*135.00 FL
14	1		*REINFORCEMENT, FR BMPR SIDE	Not Necessary	22.00 F	*- FL
15	1		*REINF, FR BUMPER SIDE, LH	Not Necessary	60.00 F	*- FL
16	1		*GRILLE ASSY, RADIATOR	Broken	550.00 F	*550.00 FL
17	1		*COVER, FR BUMPER	Not Necessary	25.00 F	*- FL
18	1		*COVER, HEADLAMP SUPT PANEL	Cut	50.00 F	*50.00 FL
19	1		*BRACKET, RADIATOR GRILLE, LH	Not Necessary	13.00 F	*- FL
20	1		*REINFORCEMENT, FR BUMPER	Not Necessary	510.00 F	*- FL
21	1		*REINF, F/BMPR SIDE, LWRLH	Not Necessary	25.00 F	*- FL
22	1		*REINFORCEMENT, FR BUMPER	Not Necessary	135.00 F	*- FL
23	1		*REINFORCEMENT, FR BMPR SIDE	Not Necessary	22.00 F	*- FL
24	1		*REINF, FR BUMPER SIDE, LH	Bent	60.00 F	*60.00 FL
25	1		*GRILLE ASSY, RADIATOR	Repeated	550.00 F	*- FL
26	1		*COVER, FR BUMPER	Repeated	25.00 F	*- FL
27	1		*COVER, HEADLAMP SUPT PANEL	Repeated	50.00 F	*- FL
28	1		*BRACKET, RADIATOR GRILLE, LH	Not Necessary	13.00 F	*- FL
29	1		*HOOD	Dented	980.00 F	*980.00 FL
30	1		*HINGE, HOOD, RH	Bent	68.00 F	*68.00 FL
31	1		*HINGE, HOOD, LH	Bent	68.00 F	*68.00 FL
32	1		*INSULATOR, HOOD	Crushed	133.00 F	*133.00 FL
33	1		*WEATHERSTRIP, HOOD, RR	Not Necessary	36.00 F	*- FL
34	1		*ROD, HOOD SUPPORT	Not Necessary	24.00 F	*- FL
35	1		*LATCH, HOOD	Not Necessary	76.00 F	*- FL
36	1		*WEATHERSTRIP, HOOD	Not Necessary	40.00 F	*- FL
37	1		*WEATHERSTRIP, HOOD	Torn	41.00 F	*41.00 FL
38	1		*FENDER, FR LH	Dented	622.00 F	*622.00 FL
39	1		*INSULATOR, FR FENDER, LH	Torn	60.00 F	*60.00 FL
40	1		*SHIELD, FR WHEELHOUSE, LH	Broken	164.00 F	*164.00 FL
41	15		*CLIP, ENG ROOM COVER	Necessary	30.00 F	*30.00 FL
42	10		*CLIP, RR BUMPER	Necessary	30.00 F	*30.00 FL
43	1		*PANEL, HEADLAMP SUPPORT, UPR	Not Necessary	183.00 F	*- FL
44	1		*PNL, HEADLAMP SUPT, UPR LH	Bent	58.00 F	*58.00 FL
45	1		*PANEL, HEADLAMP SUPPORT, LWR	Not Necessary	147.00 F	*- FL
46	1		*GARNISH, FR DECK	Broken	173.00 F	*173.00 FL
47	1		*COVER, FR DECK, LH	Not Necessary	19.00 F	*- FL
48	1		*HEADLAMP ASSY, LH	Broken	1,948.00 F	*1,948.00 FL
49	1		*LAMP ASSY, FOG, FR LH	Broken	350.00 F	*350.00 FL
50	1		*COVER, RELAY BOX	Not Necessary	52.00 F	*- FL
51	1		*BOX ASSY, RELAY	Broken	409.00 F	*409.00 FL
52	1		*CONDENSER ASSY, A/C REFRIGE	Not Necessary	861.00 F	*- FL
53	1		*RADIATOR ASSY	Not Necessary	1,020.00 F	*- FL
54	2		*INSULATOR, RDTR SUPPORT, UPR	Not Necessary	18.00 F	*- FL
55	2		*INSULATOR, RDTR SUPPORT, LWR	Not Necessary	20.00 F	*- FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*EXTENSION, FR SIDEMEMBER, LH	Not Necessary	58.00 F	*- FL
57	1		*COVER, FR BUMPER (Supplementary)	Broken	361.00 F	*361.00 FL
58	1		*GARNISH, FR BUMPER SIDE (Supplementary)	Broken	48.00 F	*48.00 FL
59	1		*GARNISH, FR BUMPER SIDE (Supplementary)	Broken	220.00 F	*220.00 FL
60	1		*RIVET, FR BUMPER (6PCS) (Supplementary)	Necessary	30.00 F	*30.00 FL
61	1		*PANEL, HEADLAMP SUPPORT, LH (Supplementary)	Bent	58.00 F	*58.00 FL
62	1		*COVER, ENG ROOM UNDER, FR (Supplementary)	Broken	349.00 F	*349.00 FL
63	1		*PAD, FR FENDER (Supplementary)	Missing	38.00 F	*38.00 FL
64	1		*BODY ASSY, AIR CLEANER (Supplementary)	Broken	146.00 F	*146.00 FL
65	1		*GARNISH, FR BUMPER SIDE (Supplementary)	Broken	112.00 F	*112.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	13,635.00
					- List Item Discount on L Items 0.00/23.00% (\$\$)	0.00
					Total Parts (\$\$)	13,635.00
						7,431.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, BONNET, FRT SUPPORT PANEL, FRT FENDER LH, WHEELHOUSING LH, REPAIR FRT DOOR LH, A-PILLAR LH	New	2,700.00	1,350.00
2	SPRAY PAINT FOR FRT BUMPER, BONNET, FRT SUPPORT PANEL, FRT FENDER LH, FRT DOOR LH, A-PILLAR LH, WHEELHOUSING LH	New	2,450.00	2,450.00
3	REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR	New	100.00	100.00
4	APPLY SEALANT FOR ACCIDENT PORTION	New	80.00	40.00
5	TOP UP AIRCON GAS	New	80.00	80.00
6	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
8	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
9	TRANSFER MAIN WIRE & RELAYS	New	450.00	450.00
10	REPLACE FRONT SUPPORT PANEL & REPAIR WHEEL HOUSING (Supplementary)	New	1,350.00	1,350.00
Gross Labour Cost (\$\$)			7,480.00	6,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >