



CYCLE & CARRIAGE

AG-OD CLAIM
SURVEY: 06/09/21
LKK - STEVE

VEHICLE NO : SGS 4242 J

MODEL : MIT/OUTLANDER 2.0 CVT

WIP : 14980

Material	:	\$	<u>7,361.97</u>
Labour	:	\$	<u>6,160.00</u>
Sub-Total	:	\$	<u>13,521.97</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>13,221.97</u>
GST 7%	:	\$	<u>925.54</u>
Grand Total	:	\$	<u>14,147.51</u>
Finalise By/Date : <u>Larry on 27/09/21</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 15 WORKING DAYS + 6 days (3 wk.ends)

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 24/09/2021	<table> <tr><td>Cust No/Name</td><td>KCV18967/MAZLAN BIN RAKIMAN</td></tr> <tr><td>Reg No/Reg Date</td><td>SGS4242J / 26/03/2021</td></tr> <tr><td>Date In/Mileage</td><td>06/09/2021/ 1110</td></tr> <tr><td>Chassis/Package</td><td>GF7W0701101 /DC17PT</td></tr> <tr><td>Engine No</td><td>4J11DA5541</td></tr> <tr><td>Make/Model</td><td>MIT/20MY OUTLANDER 2.0 CVT MODERN (997)</td></tr> <tr><td>Colour/Trim</td><td>U02 STERLING SILVER/ BK BLACK</td></tr> </table>	Cust No/Name	KCV18967/MAZLAN BIN RAKIMAN	Reg No/Reg Date	SGS4242J / 26/03/2021	Date In/Mileage	06/09/2021/ 1110	Chassis/Package	GF7W0701101 /DC17PT	Engine No	4J11DA5541	Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (997)	Colour/Trim	U02 STERLING SILVER/ BK BLACK
Cust No/Name	KCV18967/MAZLAN BIN RAKIMAN														
Reg No/Reg Date	SGS4242J / 26/03/2021														
Date In/Mileage	06/09/2021/ 1110														
Chassis/Package	GF7W0701101 /DC17PT														
Engine No	4J11DA5541														
Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (997)														
Colour/Trim	U02 STERLING SILVER/ BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	27/09/2021/ 16:06	BLC	884 / Lauro Songcuan	14980		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							1350.00
RENEW FRONT BUMPER, BONNET, FRONT FENDER LH, WHEEL HOUSING LH, REPAIR FRONT DOOR LH, A-PILLAR LH							
E PNT98000							2450.00
SPRAY PAINT FOR FRONT BUMPER, BONNET, FRONT SUPPORT PANEL, FRONT FENDER LH, FRONT DOOR LH, A-PILLAR LH, WHEEL HOUSING LH							
E PNT88000							100.00
REMOVE & INSTALL AIRCON CONDENSER AND RADIATOR ASSY							
M SUNDRY							40.00
APPLY SEALANT FOR AFFECTED PORTIONS							
A 54900099							80.00
VACUUM AND TOP UP AIRCON GAS							
A 54900099							30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
B WHEELALIGNMENT							120.00
To Conduct Computerize Full Wheel Alignment							
M SUNDRY							20.00
SUNDRIES							
A 54900099							450.00
TRANSFER MAIN WIRE & RELAYS							
S SPECIALISTJOB							50.00
SUPPLY FRONT LICENSE PLATE WITH FRAME (RECTANGULAR & BLACK)							
E PNT88000							1350.00
REPLACE FRONT SUPPORT PANEL & REPAIR WHEEL HOUSING							
X EXC							-300.00
EXCESS FOR OWN DAMAGE CLAIM							
X FACE,FR BUMPER ✓				1.00	863.00	23.00	664.51
X EXTENSION,FR BUMPER ✓				1.00	517.00	23.00	398.09
X BRACKET,FR BUMPER SIDE,RH ✓				1.00	18.00	23.00	13.86
X BRACKET,FR BUMPER SIDE,LH ✓				1.00	18.00	23.00	13.86
X GARNISH,FR BUMPER,LH ✓				1.00	48.00	23.00	36.96



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 24/09/2021	Cust No/Name	KCV18967/MAZLAN BIN RAKIMAN
	Reg No/Reg Date	SGS4242J / 26/03/2021
	Date In/Mileage	06/09/2021/ 1110
	Chassis/Package	GF7W0701101 /DC17PT
	Engine No	4J11DA5541
	Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (997)
	Colour/Trim	U02 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	27/09/2021/ 16:06	BLC	884 / Lauro Songcuan	14980
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X BRKT,FR BUMPER SIDE,LWR LH ✓		1.00	6.00	23.00	4.62 ✓
X MOULDING,FR BUMPER,LH ✓		1.00	97.00	23.00	74.69 ✓
X MOULDING,FR WHEEL ARCH,LH ✓		1.00	168.00	23.00	129.36 ✓
X REINFORCEMENT,FR BUMPER ✓		1.00	510.00	23.00	392.70 ✓
X REINF,F/BMPR SIDE,LWRLH ✓		1.00	25.00	23.00	19.25 ✓
X GRILLE ASSY,RADIATOR ✓		1.00	550.00	23.00	423.50 ✓
X COVER,HEADLAMP SUPT PANEL ✓		1.00	50.00	23.00	38.50 ✓
X HOOD ✓		1.00	980.00	23.00	754.60 ✓
X HINGE,HOOD,RH ✓		1.00	68.00	23.00	52.36 ✓
X HINGE,HOOD,LH ✓		1.00	68.00	23.00	52.36 ✓
X INSULATOR,HOOD ✓		1.00	133.00	23.00	102.41 ✓
X WEATHERSTRIP,HOOD ?		1.00	41.00	23.00	31.57 ?
X FENDER,FR LH ✓		1.00	622.00	23.00	478.94 ✓
X SHIELD,FR WHEELHOUSE,LH ✓		1.00	164.00	23.00	126.28 ✓
X CLIP,ENG ROOM COVER ✓		15.00	2.00	23.00	23.10 ✓
X CLIP,RR BUMPER ✓		10.00	3.00	23.00	23.10 ✓
X HEADLAMP ASSY,LH ✓		1.00	1948.00	23.00	1499.96 ✓
X LAMP ASSY,FOG,FR LH ✓		1.00	350.00	23.00	269.50 ✓
X BOX ASSY,RELAY ✓		1.00	409.00	23.00	314.93 ✓
X COVER,FR BUMPER		1.00	361.00	23.00	277.97 X
X GARNISH,FR BUMPER SIDE		1.00	48.00	23.00	36.96 X
X GARNISH,FR BUMPER SIDE		1.00	220.00	23.00	169.40 X
X RIVET,FR BUMPER		6.00	5.00	23.00	23.10 X
X REINF,FR BUMPER SIDE,LH ?		1.00	60.00	23.00	46.20 ?
X REINFORCEMENT,FR BUMPER ?		1.00	135.00	23.00	103.95 ?
X PANEL,HEADLAMP SUPPORT,LH → Supp.		1.00	58.00	23.00	44.66 X
X PNL,HEADLAMP SUPT,UPR LH ?		1.00	58.00	23.00	44.66 ?
X INSULATOR,FR FENDER,LH x ?		1.00	60.00	23.00	46.20 ?
X COVER,ENG ROOM UNDER,FR		1.00	349.00	23.00	268.73 X
X PAD,FR FENDER		1.00	38.00	23.00	29.26 X
X BODY ASSY,AIR CLEANER → Supp.		1.00	146.00	23.00	112.42 X
X GARNISH,FR DECK ?		1.00	173.00	23.00	133.21 ?
X GARNISH,FR BUMPER SIDE → Supp.		1.00	112.00	23.00	86.24 X

This is not an official tax invoice.
This is a computer generated document, no signature is required.




209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



THIS IS NOT AN OFFICIAL TAX INVOICE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X



CYCLE & CARRIAGE

INSURANCE CO. : **AIG**

Supplementary For Registration No.:

SGS 4242 J

Materials

- | | |
|---|-----------------------------|
| 1 | Cover, FR Bumper |
| 2 | Garnish, FR Bumper Side |
| 3 | Garnish, FR Bumper Side |
| 4 | Rivet, FR Bumper (6 pcs) |
| 5 | Panel, Headlamp Support, LH |
| 6 | Cover, Eng Room Under, FR |
| 7 | Pad, FR Fender |
| 8 | Body Assy, Air Cleaner |
| 9 | Garnish, FR Bumper Side |

Cost (\$)

361.00	—	BR
48.00	—	BR
220.00	—	BR
30.00	—	nc
58.00	—	BT
349.00	—	BR
38.00	—	MIS
146.00	—	BR
112.00	—	BR
1,362.00		
23% Discount		
313.26		
1,048.74		

Labour

- | | |
|---|--|
| 1 | Replace Front Support Panel & Repair Wheel Housing |
|---|--|

1,350.00	✓
2,398.74	
167.91	
Total	
2,566.65	

Thank You.

Yours faithfully

CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

LARRY SONGCUAN
CUSTOMER SERVICE
TEL: 6568 4658
FAX : 6567 5258

CAR NO: _____

WIP: _____

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	COVER, FR BUMPER (BLACK)	? / SUPP		✓ RR	6400J294
2	GARNISH, FR BUMPER SIDE	? / SUPP		✓ RR	6407A141
3	GARNISH, FR BUMPER SIDE	? / SUPP		✓ RR	6407A145
4	GARNISH, FR BUMPER SIDE	? / SUPP		✓ RR	6407A143
5	RIVET, FR BUMPER (X6)	? / SUPP		✓ RR	MV001657
6	REINFORCEMENT, FR BUMPER SIDE (LH)	? / SUPP		✓ RT	6400D581
7	REINFORCEMENT, FR BUMPER	? / SUPP		✓ RT	6400G576
8	PANEL, HEADLAMP SUPPORT, UPR (LH)	? / SUPP	14.9.2024	✓ RT	5215A423 5256C259
9	PANEL, HEADLAMP SUPPORT, (LH)	? / SUPP		✓ RT	5215A423
10	INSULATOR, FR FENDER (LH)	? / SUPP		✓ RR	5220K799
11	COVER, ENG ROOM UNDER, FR	? / SUPP		✓ RR	5370B626
12	COVER PAD, FR FENDER	? / SUPP		✓ RR	5220K001
13	BODY ASST. AIR CLEANER	? / SUPP		✓ RR	1500A376
14	GARNISH, FR DECK	? / SUPP		✓ RR	7405A853
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: _____

SURVEYOR: _____

CAR NO: SS4242JWIP: 14980 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Renewal fte Support to 1350 1350	? / SUPP	[Signature]	[Checkmark]	
2	Repair wheel bearings 3 days	? / SUPP			
3		? / SUPP			
4	Bray part for wheel bearing	? / SUPP	(29.22)	[Checkmark]	Star
5	Support part \$ 600	? / SUPP			
6		? / SUPP			
7	total Add 4 days = 15 days	? / SUPP			14/9/21
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: ant uderSURVEYOR: Steve

Work Order: R001537
 License: SGS4242J
 Technician: 106 WENG SOON
 Mileage: 8011
 Date: 25.9.21 16:17

Mitsubishi : Outlander/Airtrek : 2013- (GF/GG) : Front Wheel Drive

Front : Left

Actual	Before	Specified Range
0°08'	0°08'	-0°10' 0°50'
2°07'	2°07'	2°05' 3°05'
0°02'	0°00'	-0°02' 0°06'
12°12'	12°12'	11°15' 14°15'
12°20'	12°20'	11°05' 15°05'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°31'	0°31'	-0°10' 0°50'
2°48'	2°48'	2°05' 3°05'
0°02'	-0°03'*	-0°02' 0°06'
11°52'	11°52'	11°15' 14°15'
12°23'	12°23'	11°05' 15°05'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°23'	-0°24'	-0°30' 0°30'
-0°40'*	-0°40'*	-0°30' 0°30'
0°20'	0°20'	
0°03'	-0°03'	-0°04' 0°12'

Rear : Left

Actual	Before	Specified Range
-0°31'	-0°31'	-1°15' 0°15'
0°07'	0°07'	0°02' 0°12'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-0°26'	-0°25'	-1°15' 0°15'
0°09'	0°09'	0°02' 0°12'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
-0°06'	-0°06'	-0°30' 0°30'
0°17'	0°16'	0°04' 0°24'
-0°01'	-0°01'	

Work Order: R001537
 License: SGS4242J
 Technician: 106 WENG SOON
 Mileage: 8011
 Date: 25.9.21 16:17

Mitsubishi : Outlander/Airtrek : 2013- (GF/GG) : Front Wheel Drive

Front : Left

Actual	Before	Specified Range
0°08'	0°08'	-0°10' 0°50'
2°07'	2°07'	2°05' 3°05'
0°02'	0°00'	-0°02' 0°06'
12°12'	12°12'	11°15' 14°15'
12°20'	12°20'	11°05' 15°05'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°31'	0°31'	-0°10' 0°50'
2°48'	2°48'	2°05' 3°05'
0°02'	-0°03'	-0°02' 0°06'
11°52'	11°52'	11°15' 14°15'
12°23'	12°23'	11°05' 15°05'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°23'	-0°24'	-0°30' 0°30'
-0°40'	-0°40'	-0°30' 0°30'
0°20'	0°20'	
0°03'	-0°03'	-0°04' 0°12'

Rear : Left

Actual	Before	Specified Range
-0°31'	-0°31'	-1°15' 0°15'
0°07'	0°07'	0°02' 0°12'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-0°26'	-0°25'	-1°15' 0°15'
0°09'	0°09'	0°02' 0°12'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
-0°06'	-0°06'	-0°30' 0°30'
0°17'	0°16'	0°04' 0°24'
-0°01'	-0°01'	

All DTCs

Reg 101 SCS 42425

Before using MUT-3 VCI unit to check all the DTCs

2021.09.24

Setting	
Item	Information
M.U.T.-3 Version	SEW21031-00
V.C.I. Version	B179
Vehicle Information	DBA-GFTW 2020MY

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
OSS	OSS_9588000B		No DTCS		
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error		
ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error		
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error		
EPB	EPB_4C080000		No DTCS		
Gateway	GW_C1000000		Non-equipped System or Communication Error		
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error		
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error		
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error		

All DTCS

Setting	
Item	Information
M.U.T.-3 Version	SEW21031-00
V.C.I. Version	B179
Vehicle Information	DBA-GF7W 2020MY

Reg No. 868 42423

After repair to

Check on electronic Crtl

8/24

to use MUT-3 ver int to Reg
all the good
as Job Done

2021.09.24

All DTCS

2021.09.24

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
OSS	OSS_9588000B		No DTCS		
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error		
ACC/FCM	ACC/FCM_4B080000		Non-equipped System or Communication Error		
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error		
EPB	EPB_4C080000		No DTCS		
Gateway	GW_C1000000		Non-equipped System or Communication Error		
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error		
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error		
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error		