

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21009332/VGA3Q2**Date:** 18/04/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210081572
<b>Claimant Vehicle No :</b>	SH7769C	<b>Insured Vehicle No :</b>	GBE8523E
Date of Loss:	04/09/2021	Nature of Claim:	TP
		Claim No:	2726171362SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SH7769C</b>	Engine No:	G4LEKU407483
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Chassis No:	KMHC851CVLU189552
Reg. Date:	11/03/2020 (Man. Year: 2019)	Odometer:	162107 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,170.52	1,259.60	3,910.92	75.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,760.00	1,230.00	530.00	30.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,930.52</b>	<b>2,489.60</b>	<b>4,440.92</b>	<b>64.08</b>
<b>+ GST 7.00/7.00% (S\$)</b>	485.14	174.27	310.87	64.08
<b>Nett Amount (S\$)</b>	<b>7,415.66</b>	<b>2,663.87</b>	<b>4,751.79</b>	<b>64.08</b>
<b>+ Loss of Use (4.0 x S\$50.00/day) (S\$)</b>		200.00		
<b>+ Car Rental (4.0 x S\$125.19/day) (S\$)</b>		500.76		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,366.63</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,350.00</b>		

**INSPECTION**

Date of Assignment:	06/09/2021	
Date Inspected:	06/09/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

**Adjuster:** Thevan Thomas Karthikesavan**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID ASSY	Repair	2,480.40 FL	*- FL
2	1		*BOOT LID EMBLEM -HYBRID	Necessary	24.30 FL	*24.30 FL
3	1		*BOOT LID EMBLEM -LONIQ	Necessary	31.30 FL	*31.30 FL
4	1		*BOOT LID LOWER GLASS (BLACK)	Serviceable	584.90 FL	*- FL
5	1		*REAR BUMPER	Cut	459.40 FL	*459.40 FL
6	1		*REAR BUMPER REINFORCEMENT	Serviceable	394.80 FL	*- FL
7	2		*REAR BUMPER REINFORCEMENT BRACKET RH/LH	Serviceable	276.20 FL	*- FL
8	1		*REAR BUMPER CENTRE MOULDING ASSY	Cut	451.25 FL	*451.25 FL
9	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Cut	155.00 FL	*155.00 FL
10	10		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
11	1		*REAR BUMPER REFLECTOR LAMP RH	Serviceable	41.45 FL	*- FL
12	1		*BOOT LID LAMP RH	Serviceable	794.40 FL	*- FL
13	1		*REAR BUMPER FOG LAMP	Serviceable	201.50 FL	*- FL
14	1		*BOOT LID COMFORTDELGRO	Necessary	35.00 FS	*35.00 FS
15	1		*BOOT LID 65521111	Necessary	35.00 FS	*35.00 FS
16	1		*BOOT LID APPS	Necessary	40.00 FS	*40.00 FS
17	1		*REAR BUMPER REVERSE SENSOR	Cut	180.00 FS	*180.00 FS
18	1		*REAR NO PLATE W/TRIM COVER	Cracked	55.00 FS	*55.00 FS
19	2		*REAR WINDSCREEN SEALANT	Not Applicable	92.00 FS	*- FS
					Sub Total (S\$)	6,353.90 1,488.25
					- List Item Discount on L Items 20.00/20.00% (S\$)	1,183.38 228.65
					Total Parts (S\$)	5,170.52 1,259.60

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	800.00	700.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
4	REMOVE /REFIX BOTH REAR GLASSES	New	240.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,760.00</b>	<b>1,230.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >